DEPRESS THE OFF NEY, TO TURN OFF THE SCALE.	AFTER GRAVITY VALUE IS ADJUSTED. HIT THE ROYID XEY CACE.	THE DIFFERENCE OF GRAVITY VALUE CAN BE DISPLAYED BY PRESSING EITHER THE A OR V NEW PLUS OR MINIS 0.22 % RANGE.)	SELECT [+] OR [-] CODE ALTERNATELY BY PRESSING THE TARE KEY.	DEPRESS THE kg/16 KEY ONCE.	PUSH THE ( A KEY THICE.	F I WILL APPEAR ON THE DISPLAY. RELEASE THE TARE NEY AND THE UNIT WILL BE ACTIVATED.	HOLD DOWN THE TARE KEY AND DEPRESS THE DOW/ZERO KEY	KEY OPERATIONS
	ANY NUMBER	0.10 -+ 0.1% -020 0.2%	(-) <del>- [200 -</del> (-)	5002 sname	E 3	F	88888	DISPLAY


25304401





### **Electronic Digital Scale** NTEP APPROVED CLASS III MODEL No. BWB-627A

THIS INSTRUCTION IS ONLY FOR AUTHORIZED PERSONNEL) SERVICE MANUAL \*



THIS FINE INSTRUMENT IS PRECISION CRAFTED BY FANITA CORPORATION, TOKYO, JAPAN


### \* NOITHBILLY

# THE GRAVITY CALIBRATION MUST BE HADE EACH TIME AFTER TOLERANCE ADJUSTMENT HAS BEEN CONCLUDED.


THE DIFFERENCES OF GRAVITY IN PERCENTAGES MUST BE ADJUSTED TO O. OOK WHEN THE SCALE IS TRANSFERED FROM ONE LOCATION TO ANOTHER OR THE GRAVITY CALIBRATION CAN BE MADE BEFORE THE TRANSFER.

# TO ENTER CALIBLATION MODE

1. AS ILLUSTRATED BELOW. LOOSEN THE SCREW OF THE SWITCH COVER. UNDERNEATH THE COVER. YOU CAN FIND THE MODE SWITCH.



2. BY SLIDING THE MODE SWITCH UPWARD, THE SCALE WILL AUTOMATICALLY BE IN THE CALIBRATION MODE.



INPORTANT: THE SWITCH SHOULD BE RETURNED TO ORIGINAL POSITION AFTER CALIBRATION BEING FINISHED.

## TOLERANCE ADJUSTMENT

Cos	7.	ற	ប្	<i>-</i>	,ω [	.2	-	
REMOVE THE WEIGHT/S AND CLEAR THE PLATFORM.  PRESS THE OFF KEY.  COMPLETED TOLERANCE ADJUSTMENT.	PUSH THE Kg/16 KEY WHEN KEIGHT IS STABILIZED.	GENTLY PLACE THE CORRECT NEIGHT WHICH YOU SELECTED IN STEP No. 4 ON THE CENTER OF THE PLATFORM	PRESS THE KRYTED KEY TWO TIMES.	HIT THE K9716 KEY ONCE.  THE MANIFOLD SHOW IN THE DISPLAY CAN BE CHANGED BY PRESSING  THE A OR Y KEY DEPENDING ON THE TYPE OF  MEASUREMENT WHICH YOU HAVE SELECTED.  NOTE: THE MEIGHT MIST BE WITHIN THE RANGE OF MALF CAPACITY TO  FULL CAPACITY.	PUSH THE KRY ID KEY ONCE.  PRESS THE TARE KEY ALTERNATELY FOR LB OR KG KEIGHTS TO BE USED FOR CALIBRATION.	DEPRESS THE KEY CALY CICE.	HOLD DOWN THE TARE KEY AND DEPRESS THE ON ZERO KEY SIMULTANEOUSLY.  F I) YILL BE DISPLAYED.  RELEASE THE TARE KEY.	KEY OPERATIONS
	WY NUMBER	2		ECUPLE:  EC	APPEARS:  (1)	FZ	F 88888	OISPLAY



TARE WEIGHING (How to weigh an object)

Tare weighing can be continuously on for a new object by switching TARE button but within 134.9kg (or 299.8Lb).

- \* Push "ON/ZERO" switch.
- \* Step on the scale and push "TARE" switch. Net mark (◀) appears on the display and the reading returns to 0.0.
- \* Hold the object and stand still until the weight of the object is displayed.

### TARE PRESET WEIGHING

- \* Push "ON/ZERO" switch.
- \* Push "TARE PRESET" switch, then Net mark (◄) will flash and a numeral will be displayed. During the time when the Net mark flashes, the weight you want can be deducted by Up (▲) or Down (▼) switch before you start weighing.
- \* As soon as the weight deducted is displayed, push "TARE PRESET" switch again, and then scale displays minus (-) numerals.
- \* Step on the scale and stand still until your net weight is displayed.

NOTE: TARE and TARE PRESET weighing mode have limited range, which is up to 134.9kg (or 299.8Lb).

AUTO POWER OFF (saving energy)

The scale automatically shuts off when the scale is not in operation for 10 minutes.

### **REMARKS**

"----"message appears in the display when weight is in excess 105% of the scale capacity.

If not use for long term, remove battery to prevent corrosion on battery contacts.