
Operating instructions and installation information

METTLER TOLEDO MultiRange ID7-Base weighing terminal





The weighing terminal 22001373A consists of:

ID7-Desk BasePac-ID7 IDNet-ID7 RS232-ID7

Contents

	Р	age
1	Introduction and commissioning	3
1.1	Safety precautions	3
1.2	Applications	3
1.3	ID7-Base weighing terminal	4
1.4	Commissioning	6
1.5	Cleaning	7
2	Basic functions	8
2.1	Switching on and off	8
2.2	Setting to zero	8
2.3	Taring	(
2.4	Weighing	10
2.5	Switch over weighing platform	10
3	Additional functions	11
3.1	Weighing with the DeltaTrac	11
3.2	Dynamic weighing	14
3.3	Change weight unit	14
3.4	Working in a higher resolution	18
3.5	Display gross weight	18
3.6	Multiplicative tare function	18
3.7	Additive tare function	18
3.8	Sandwich tare	16
3.9	Display ID code and test weighing platform	16
3.10	Identifications	16
3.11	Recall information	18
3.12	Print or transfer data	19
3.13	Enter values with barcode reader	19
3.14	Working with external keypad	20
3.15	Working with a second display	2
4	Settings in the master mode	22
4.1	Overview of the master mode	22
4.2	Operating the master mode	23
4.3	TERMINAL master mode block	24
4.4	SCALE master mode block	28
4.5	INTERFACE master mode block	3
5	Interface description	40
5.1	MMR command set	4(
5.2	METTLER TOLEDO continuous mode	52

Contents ID7-Base

6	Application blocks	54
6.1	Syntax and formats	54
6.2	TERMINAL, SCALE application blocks	56
6.3	INTERFACE application blocks	59
7	What to do if?	61
8	Technical data and accessories	64
8.1	Technical data	64
8.2	Accessories	68
9	Appendix	72
9.1	Fix-tare	72
9.2	Delta-fix	73
9.3	Fixed texts	74
9.4	Table of representable characters	75
9.5	Opening/closing ID7-Base weighing terminal	76
9.6	Configuring Pin 5 on RS232-ID7 interface	76
10	Index	77

1 Introduction and commissioning


1.1 Safety precautions



- ▲ Never operate the ID7-Base weighing terminal in hazardous areas; there are special scales in our product line for this purpose.
- ▲ Make sure that the electrical outlet for the ID7-Base weighing terminal is grounded and easily accessible to that it can be isolated quickly in emergencies.
- ▲ Make sure that the mains voltage at the installation location is within the range from 100 V to 240 V.
- ▲ The safety of the unit is endangered if it is not operated in accordance with these operating instructions.
- ▲ Only authorized personnel may open the ID7-Base weighing terminal.

1.2 Applications


With the ID7-Base weighing terminal the following applications are possible:



- Multi-scale operation with up to 3 weighing platforms, including a weighing platform with an analog signal output.
- Up to 6 data interfaces
 - for printing,
 - for data exchange with a computer,
 - for connecting a barcode reader,
 - for control, e.g. of valves or flaps.
- Comfortable alphanumeric entry via an external keypad.

1.3 ID7-Base weighing terminal

1.3.1 Display




- 1 Weight display BIG WEIGHT DISPLAY with sign and decimal point
- **2** Stability monitor: lights up until the weighing platform has levelled out, then the weight unit appears here
- 3 Number of the weighing platform: shows the weighting platform just selected
- 4 NET symbol for marking net weight values
- **5** Assignment of the function keys

1.3.2 Keypad



- 1 CODE A ... CODE D keys enter identification data
- 2 ON/OFF On/Off key
- **3** FUNCTION CHANGE key display additional functions when entering weight values: switch over unit
- **4** INFO key recall memory contents and system information
- **5** Function keys F1 \dots F6 the current assignment is shown in the display above the key
- **6** SCALE key select scale
- **7** ZERO-SET key set scale to zero, test scale
- 8 TARA key tare scale
- **9** TARE SPECIFICATION key enter known tare values numerically
- **10** CLEAR key clear entries and values
- 11 ENTER key accept and transfer data
- 12 Numeric keypad with decimal point and signs

1.3.3 Connections



- 1 Connection for the external MFII keypad
- 2 Connection for weighing platform 1
- **3** Optional connections for weighing platform 2 and 3
- 4 5 optional interface connections
- 5 Standard RS232 interface
- 6 Power supply

Possible assignments for serial interfaces

Interface	сом1	COM2	сомз	COM4	COM5	сом6
CL20mA-ID7	_	х	Х	х	х	х
RS232-ID7	Х	Х	Х	х	Х	х
RS422-ID7	_	_	_	_	х	х
RS485-ID7	_	_	_	_	Х	х
RS485-ID7 with relay box 8-ID7	_	_	_	_	_	Х
4 I/O-ID7	_	_	_	_	Х	х
Analog Output-ID7	_	_	_	_	Х	х
Alibi Memory-ID7	_	Х	Х	Х	Х	Х

Notes

- COM1 is permanently equipped with the serial interface RS232-ID7 as standard.
- Only one Alibi Memory ID7 can be installed. It has no additional external connection, and internally it occupies the space of a data port COM2 ... COM6. Alibi Memory ID7 is installed as COM4 at the factory.

CAUTION

→ Cover unused connection sockets with protective caps to protect the socket contacts from moisture and dirt.



1.4 Commissioning

1.4.1 Connect weighing platforms of the series D, F, K, N, Spider ID and AWU3/6

- 1. Set up weighing platform, see installation instructions of weighing platform.
- 2. Route weighing platform cable to weighing terminal.
- 3. Plug in weighing platform connector on weighing terminal.

1.4.2 Connect scales of the series B, G, R and DigiTOL

Precision scales of the **series B, G and R** can be connected to the ID7-Base weighing terminal with the LC-IDNet B or LC-IDNet R/G connection set.

To connect **DigiTOL** scales, the GD17 connection set is required.

- 1. Set up scale, see operating instructions of scale.
- 2. Connect appropriate connection set to scale.
- 3. Route cable of connection set to weighing terminal and plug in.

1.4.3 Commissioning with several weighing platforms

→ To start up the ID7-Base weighing terminal with several weighing platforms, please contact METTLER TOLEDO Service.

1.4.4 Connect ID7-Base to network



CAUTION

The ID7-Base weighing terminal only functions properly with mains voltages of 100 V to 240 V.

- → Make sure that the mains voltage at the installation location lies within this range.
- → Make sure that the mains outlet is grounded and easily accessible.

Connecting

→ Plug mains plug of ID7-Base into a mains outlet.

In the factory setting the display briefly shows METTLER TOLEDO ID7 and the versions of the installed components; then the weight display appears.

1.4.5 Marking and sealing of certified weighing platforms

ID code

With the ID code it can be checked whether certified weighing platforms have been tampered with since the last calibration. The ID code can be displayed on the terminal at any time, see section 3.9.

During calibration the currently displayed ID code is recorded and sealed.

During each change to the configuration the displayed ID code increases. It then no longer matches the sealed ID code; the calibration is not longer valid.

Certification


To mark and certify your weighing system, please contact METTLER TOLEDO Service or your local board of weights and measures.

Check certification

1. Display ID code, see section 3.9; press ZERO-SET key until IDENTCODE = ... is displayed.

No value is shown for noncertified weighing platforms, but instead: IDENTCODE ===.

Compare ID code displayed with sealed ID code on ID card.
 The certification of the weighing system is only valid when both values are identical.



3. Press ZERO-SET key again.

The connected weighing platform is checked. The display shows CHECK SCALE and after the test is completed SCALE IS OK.

Then the ID7-Base automatically returns to normal operation.

1.5 Cleaning



DANGER OF SHOCK

→ Do not open ID7-Base weighing terminal to clean.

CAUTION

- → Make sure that unused connection sockets are covered with protective caps to protect the socket contacts from moisture and dirt.
- → Do not use high-pressure cleaners.

Cleaning

→ Wipe of ID7-Base weighing terminal with a commercially available glass or plastic cleaner.

Basic functions ID7-Base

2 Basic functions

2.1 Switching on and off

Switch on from the standby mode

→ Press ON/OFF key.

The display shows a weight value based on the last tare value and zero point.

Switch on with restart

- 1. Relieve weighing platform.
- Press ON/OFF key and hold down until METTLER TOLEDO ID7 (factory setting) or text you have specified appears in display.

Then weight value 0.000 kg appears.

The weighing platform is restarted.

Note

The text which appears during switch-on with a restart is saved in the text memory 20, see section 4.3.2.

Switch off

→ Press ON/OFF key.

The display goes out and the ID7-Base weighing terminal is in the standby mode. The zero point and tare value remain saved.

2.2 Setting to zero

Setting to zero corrects the influence of minor dirt on the load plate.

In the case of excessive dirt which cannot be compensated by setting to zero, the display shows OUT OF RANGE.

Manual zero set

- 1. Relieve weighing platform.
- Press ZERO-SET key. The display shows 0.000 kg.

Automatic zero set

On certified weighing platforms the zero point of the weighing platform is automatically corrected when the weighing platform is relieved.

The automatic zero set can be switched off in the master mode on noncertified weighing platforms.

ID7-Base Basic functions

2.3 Taring

2.3.1 Manual taring

- 1. Place empty container on scale.
- 2. Press TARE key.

The tare weight is saved and the weight display set to zero.

The display shows the NET symbol.

Notes

- When the weighing platform is relieved, the saved tare weight is displayed with a negative sign.
- The weighing platform only saves **one** tare value.

2.3.2 Automatic taring

Prerequisite

AUTOTARA ON must be set in the master mode, see section 4.4.

→ Place empty container on scale.

The container weight is automatically saved and the weight display set to zero. The display shows the NET symbol.

Note

When the weighing platform is relieved, the saved tare weight is cleared.

2.3.3 Specify tare weight

Enter numerically

- 1. Press TARE SPECIFICATION key.
- Enter tare weight (container weight) and confirm with ENTER.When weighing platform is relieved, the entered tare weight is displayed with a negative sign.

Note

With the FUNCTION CHANGE key you can select the weight unit for entering the tare weight.

Correct entry

→ Clear the entry character by character with the CLEAR key and repeat correctly.

Copy tare constant

The ID7-Base has 25 Tara memories for frequently used tare weights programmed in the master mode. The programmed tare constants are listed in the table in the Annex.

- 1. Enter memory number: 1... 25.
- Press TARE SPECIFICATION key. The display shows the NET symbol and the net weight based on the recalled tare weight.

Basic functions ID7-Base

2.3.4 Recall currently saved tare weight

The saved tare weight can be recalled at any time.

→ Enter INFO, TARE SPECIFICATION key sequence. The saved tare weight is displayed.

2.3.5 Clear tare weight

- → Relieve weighing platform and tare.
- or -
- → Specify tare weight 0.
- or -
- → Enter TARE SPECIFICATION, CLEAR key sequence.

2.4 Weighing

Weighing without taring

→ Lay weighing sample on weighing platform.

Gross weight (total weight) is displayed.

Weighing with taring

- 1. Place the empty container on the weighing platform and tare.
- Pour in weighing sample.The display shows the net weight and the NET symbol.

Weighing with tare specification

- Place filled container on weighing platform.
 The display shows the gross weight (total weight).
- Specify tare weight or recall tare memory.The display shows the net weight (container content) and the NET symbol.

2.5 Switch over weighing platform

Up to 3 weighing platforms can be connected to the ID7-Base. The weighing platform currently selected is shown on the terminal.

- → Press SCALE key.

 The next weighing platform is selected.
- or -
- → Enter number of weighing platform and press SCALE key. The desired weighing platform is selected.

ID7-Base Additional functions

3 Additional functions

The assignment of the 6 function keys of the ID7-Base weighing terminal differs depending on the weighing task. The current assignment is shown above the function keys.

With the FUNCTION CHANGE key it is possible to switch over to other function key assignments.

Independent of the application software, the ID7-Base has the following additional functions:

DELT	DYN	UNIT	X 10	GROSS	MODE
Weighing with the DeltaTrac, see 3.1	Dynamic weighing, see 3.2	Change weight unit, see 3.3	Increase res- olution, see 3.4. This key is not as- signed when the control mode is con- tinually switched on.	Display gross weight, see 3.5	Activate master mode, see Chapter 4

MULT-TARE	ADD-TARE	SANDWICH-T
Multiplicative tare function, see 3.6	Additive tare function, see 3.7	Sandwich tare, see 3.8

3.1 Weighing with the DeltaTrac

The DeltaTrac is an analog display which makes it easier to read the weighing results.

In the master mode you can select how the DeltaTrac is displayed for the various weighing tasks FILLING, CLASSIFYING or CHECKWEIGHING.

Notes

- With the DeltaTrac signals you can also control lamps, flaps or valves, see section 4.5.4.
- With the Analog Output-ID7 interface the net value can be output as an analogue current or voltage signal.

Additional functions ID7-Base

Application FILLING

For weighing-in to a target weight with tolerance monitoring.


Example: Target weight = 1.000 kg, tolerance = 1 %



Application CLASSIFYING

To evaluate test samples as OKAY, TOO LIGHT or TOO HEAVY, based on a target weight and specified +/- tolerances.


Example: Target weight = 1.000 kg, tolerance = 1 %



Application CHECKWEIGHING

For determining the difference between the target and actual weight.

Example: Target weight = 1.000 kg, tolerance = 1 %



ID7-Base Additional functions

3.1.1 Preset DeltaTrac target values

Enter numerically

- 1. Press DELT key.
- 2. Enter target weight and confirm with ENTER.
- 3. Enter tolerance in % of target weight and confirm with ENTER.

Note

With the FUNCTION CHANGE key you can select the weight unit for entering the DeltaTrac target values.

Correct entry

→ With the CLEAR key the entry is corrected character by character.

Copy constants

The ID7-Base weighing terminal has 25 DeltaTrac memories for frequently used target values and tolerances, which are programmed in the master mode. The programmed DeltaTrac constants are specified in the list in the Annex.

- 1. Enter number of DeltaTrac memory: 1 ... 25.
- 2. Press DELT key.

Reference sample

- 1. Press DELT key.
- 2. Lay sample on weighing platform and confirm with SCALE key.
- 3. Only for FILLING and CLASSIFYING: Enter tolerance and confirm with ENTER.
- 4. Remove sample from weighing platform.

Limits

Minimum target value 40 Digit

Maximum target value configured maximum load

Minimum tolerance 1 Digit

Maximum tolerance 10 % for the applications FILLING, CHECKWEIGHING

50 % for the application CLASSIFYING

Note

If the limits are not observed, a message appears in the display, e.g. MIN-DEL = ..., for too small a target value.

Clear DeltaTrac target value

→ Press DELT CLEAR key sequence.

DELTA CLEARED appears briefly in the display, then the weight is shown.

Additional functions ID7-Base

3.2 Dynamic weighing

With the dynamic weighing function you can weigh restless weighing samples, e.g. live animals. To do this, specify the number of weighing cycles for which the mean weight value is to be taken.

- 1. Set container on the weighing platform.
- 2. Tare weighing platform.
- 3. Place weighing sample in container.
- 4. Press DYN key and enter number of weighing cycles.

Possible values: 1 ... 255.

- 5. Start dynamic weighing with ENTER key.
- After cycle time has expired, center line of display shows:
 RESULT x.xxxx kg.
 This display is retained until the next weighing is started or until it is cleared.

Delete result

→ Press CLEAR key.

Notes

- Dynamic weighing results are automatically printed when AUTO PRINT is set in the master mode, see section 4.3.2.
- During dynamic weighing it is not possible to display the weight value BIG WEIGHT DISPLAY, which fills the entire display.
- Dynamic weighing can also be started with the interface command AW016..., see section 6.2.

3.3 Change weight unit

If an additional, second weight unit is configured in the master mode, it is possible to switch back and forth between the two weight units.

→ Press UNIT key.

The weight value is shown in the second unit.

Note

Possible second weight units are: g, kg, lb, oz, ozt, dwt.

ID7-Base Additional functions

3.4 Working in a higher resolution

Depending on the setting in the mastermode (see page 27), the weight value can be displayed in a higher resolution continuously or when called.

Weight values in a higher resolution are marked with a *.

Displaying weight values in higher resolution

→ Press X 10 key.

The weight value is displayed in at least a 10x higher resolution. The higher resolution is displayed until the X 10 key is pressed again.

Note


With certified weighing platforms, the weight value only appears in a higher resolution as long as the X 10 key is pressed.

3.5 Display gross weight

The gross weight can only be displayed when a tare weight has been saved.

→ Press GROSS key and hold down. The gross weight is displayed.

3.6 Multiplicative tare function




The multiplicative tare function is particularly suitable when pallets with identical containers are filled. If the number of containers and tare of the individual container are known, the ID7-Base weighing terminal calculates the total tare.

- 1. Press MULT TARE key.
- 2. Enter known tare weight of individual container and confirm with ENTER.
- Enter number of containers and confirm with ENTER.
 When the weighing platform is relieved, the total tare value is shown in the display with a negative sign.

Note

With the FUNCTION CHANGE key you can select the weight unit for entering the tare weight.

3.7 Additive tare function



With the additive tare function you can subtract the tare of additional containers with a know tare weight for related weighings, e.g. if containers with different weights are filled on one pallet.

- 1. Place container on scale and press ADD TARE key.
- 2. Enter known tare weight and confirm with ENTER.


 The total net weight appears in the weight display.

Note

With the FUNCTION CHANGE key you can select the weight unit for entering the tare weight.

Additional functions ID7-Base

3.8 Sandwich tare



With the sandwich tare function you can detect additional tare weights for related weighings without loosing the total gross and total net.

Example

In production or shipping boxes are laid between individual layers in the transport container. The weight of these boxes can be subtracted with this function.

- 1. Press SANDWICH-T key.
- 2. Place sandwich tare, e.g. box, on scale and confirm with ENTER. The net weight is retained.

3.9 Display ID code and test weighing platform

Each time the weighing platform configuration is changed the ID code counter is increased by 1. On certified weighing platforms the displayed ID code must match the ID code on the ID code sticker, otherwise the calibration is no longer valid.

Display ID code

→ Press ZERO-SET key and hold until IDENTCODE = ... appears in the display.

Test weighing platform

→ Press ZERO-SET key again. The connected weighing platform is checked. The display shows CHECK SCALE and then SCALE IS OK after completing the test.

Note

If weighing platform is defective, display shows SCALE ERROR.

3.10 Identifications

The ID7-Base weighing terminal is equipped with 4 identification data memories for storing identification data Code A ... Code D.

The memories have a name, e.g. Article No., and a content which identifies the current weighing, e.g. 1234567.

The memories are named in the mastermode, and the names can be noted on the keyboard. When the CODE keys are pressed, the name appears in the display. Identification data Code A ... Code D can be entered or recalled for each weighing and are printed immediately.

3.10.1 Enter identification

An identification may contain a maximum of 20 characters.

Enter numerical identification

- 1. Press one of the keys CODE A ... CODE D.
- 2. Enter identification data Code A ... Code D via the numeric keypad and confirm with FNTFR.

ID7-Base Additional functions

Enter alphanumeric identification

Press one of the keys CODE A ... CODE D.
 The functions keys are given the following assignment:

ABCDE	FGHIJ	KLMNO	PQRST	UVWXY	Z /-()
Selection of letters A to E	Selection of letters F to J	Selection of letters K to O	Selection of letters P to T	Selection of letters U to Y	Selection of letters Z and special characters

- 2. Select desired group of letters, e.g. press KLMNO key.
- 3. Select desired letter.

 The display changes again to the above selection.
- 4. Repeat entry in steps 2 and 3 for additional characters.

Note

Letters and numbers can be combined as desired.

Recall fixed text memory

The ID7-Base weighing terminal is equipped with 20 memories for fixed texts which can be programmed in the master mode and used as identifications.

The programmed fixed texts are specified in the list in the Annex.

- 1. Enter memory number.
- Press a key CODE A ... CODE D.
 The saved fixed text is now assigned to the selected identification Code A ... Code D.

Other entry possibilities

Identifications can also be entered with a barcode reader, see section 3.13, or with an external keypad, see section 3.14.

3.10.2 Clear identifications

→ Press desired key CODE A ... CODE D and clear memory content with CLEAR key.

Additional functions ID7-Base

3.11 Recall information

On the ID7-Base weighing terminal memory contents and system information can be recalled.

Press INFO key.

Then the following function key assignment appears:

DELT	TARE	TEXT	ALIBI	DATE	VERS
Display DeltaTrac values	Display tare weight	Display fixed texts and name of keys CODE A CODE D	Recall content of alibi memory. This selection only appears when Alibi Memory-ID7 is installed.	Display date and time	Display version numbers of installed software modules

2. Select desired information.

The information is displayed for approx. 5 seconds, then the ID7-Base changes to the weighing mode again.

Notes

- When several values are displayed, the ID7-Base automatically changes to the next value after approx. 5 seconds.
- With the CLEAR key it is possible to switch to the next value or back to the weighing mode.
- When the GA46 printer is connected, the version numbers of the installed software modules are automatically printed.

3.11.1 Recall memory

- 1. Press INFO key.
- 2. Enter number of memory and press DELT, TARA or TEXT key depending on desired memory.

Recall name of CODE A ... CODE D keys

- 1. Press INFO key.
- 2. Press one of the keys CODE A ... CODE D. The display shows the current Code.

ID7-Base Additional functions

3.12 Print or transfer data

If a printer or computer is connected, weighing results can be printed out or transferred to the computer. In the master mode you can set the following for this purpose:

- Data to be printed or transferred,
- Manual or automatic data transfer,
- Key which triggers printing or data transfer.

Factory setting

- Manual triggering with the ENTER key.
- The content of the display is transferred or printed.

3.13 Enter values with barcode reader

If you have connected a barcode reader to the ID7-Base weighing terminal, you can make all required entries, such as identifications or target specifications, easily with the barcode reader.

3.13.1 Read in any desired entries with the barcode reader

Example Read in identification Code A

- 1. Press CODE A key; the ID7-Base expects the entry of Code A.
- 2. Enter identification Code A with the barcode reader.
- 3. Confirm barcode entry with ENTER.

3.13.2 Read in a frequently used entry directly with the barcode reader

If your working procedure repeatedly requires the same entry, you can configure the barcode reader in the master mode (see section 4.5.3) so that no additional keys need to be pressed on the ID7-Base terminal for barcode entry.

Example Barcodes are automatically read in as Code A

If the working procedure requires the entry of Code A:

→ Enter identification Code A with barcode reader.

The read-in information is automatically processed by ID7-Base as Code A.

Additional functions ID7-Base

3.14 Working with external keypad

In addition to the alpha and numerical keys, the following additional scale functions can also be operated with the external AK-MFII keypad.

Function for ID7-Base	External keypad	Function for ID7-Base	External keypad
Function key F1	F1	CODE A key	Shiff F1
Function key F2	F2	CODE A key	Shiff F2
Function key F3	F3	CODE A key	Shiff F3
Function key F4	F4	CODE A key	Shift F4
Function key F5	F5		
Function key F6	F6		
FUNCTION CHANGE key	F7		
INFO key	F8		
SCALE key	F9	SCALE key	Shiff F9
ZERO-SET key	F10	ZERO-SET key	Shiff F10
TARE key	F11	TARE key	Shiff F11
TARE SPECIFICATION key	F12	TARE SPECIFICATION key	Shiff F12

Note

The language of your external keyboard can be set in the mastermode block LAYOUT EXT. KEYBOARD, see page 26.

ID7-Base Additional functions

3.15 Working with a second display

An ID1 Plus, ID3s or another ID7-... weighing terminal can be connected to the ID7-Base as a second display.

Conditions

- Interface CL 20mA-ID7 installed in passive operating mode (factory setting).
- AUTO-DIR setting selected in mastermode (see page 33).
- Weighing terminal is connected as second display with cable 00 504 511.

Operation possibilities on second display

The following functions are also possible on the second display:

- · Set to zero
- Taring


ID7-... as second display

With ID7-... as a second display, the weight value fills the entire display (BIG WEIGHT DISPLAY ON).

4 Settings in the master mode

4.1 Overview of the master mode

In the master mode you adapt the ID7-Base weighing terminal to meet your needs. Depending on the configuration, the master mode is divided into 4 or 5 master mode blocks, which are in turn divided into further blocks.



TERMINAL For system settings, such as entering the date and time or loading permanent texts, see section 4.3.2.

PAC To set application-specific parameters.

This block does not appear with ID7-Base.

SCALE To select one of the connected weighing platforms. For each selected weighing platform the parameters are then set which concern the weight value, e. g. stability detector, unit, etc., see section 4.4.

INTERFACES To select an interface. The communication parameters are then set for each interface, see section 4.5.

SERVICE For configuring the weighing platform(s). On IDNet weighing platforms only for METTLER TOLEDO service technicians.

4.2 Operating the master mode

4.2.1 Enter the master mode

- Press MODE key.
 If the current function key assignment does not contain MODE, change to the assignment with MODE by repeatedly pressing the FUNCTION CHANGE key.
- Enter personal code if configured.The display shows the first master mode block TERMINAL.

4.2.2 Assignment of function keys in the master mode

In the master mode the function keys are assigned as follows:

←	\rightarrow	↑	END	ОК
Change to previous block within a level	Change to next block within a level	Exit level and return to higher-level block	Exit the master mode and return to normal mode	Recall lower- level block or confirm selection

→ Select the function by pressing the function key.

Example

→ Press the END key to exit the master mode and return to the normal mode.

When the function keys are otherwise allocated


→ Press the key FUNCTION CHANGE until the function keys allocation displayed above appears.

4.2.3 Orientation in the master mode

For improved orientation the display shows the last steps in the path of the current master mode block.

Example

The upper 3 lines of the display show the following path for selecting the DeltaTrac application FILLING:



4.2.4 Entries in the master mode

The following basic rules apply to entries made in the master mode:

- Confirm (alpha)numeric entries with ENTER.
- Alphanumeric entries with the ID7-Base: see section 3.10.
- To accept the displayed value: Press ENTER key.

4.2.5 Emergency entrance into the master mode


If a personal code has been assigned for entering the master mode and you have forgotten your code, you can still enter the master mode:

→ Enter the character sequence C, L, E, A, R as your personal code.

4.3 TERMINAL master mode block

4.3.1 Overview of the TERMINAL master mode block

In the TERMINAL master mode block you enter the following system settings:



• Blocks highlighted in **grey** are described in detail in the following.

• Factory settings are printed in **bold print**.

4.3.2 Settings in the TERMINAL master mode block

RESET TERMINAL	Reset all terminal function	Reset all terminal functions to the factory setting			
	DELTATRAC BIG WEIGHT DISPLAY DYNAMIC WEIGHING CONTROL MODE	Filling On No printout X 10 key			
Comment	The memories are not affected by this.				

FIX-TARE	Save tare values protected against power failure to tare memories	
CLEAR ALL TARES	Delete all tare memories.	
LOAD FIX-TARE	1. Enter memory number of FIX-TARE No.: 1 25.	
	Enter tare weight for the selected memory in the displayed unit.	
	3. To load additional fixed tare values, repeat the first two steps.	
	4. End entry: Confirm FIX-TARE NO. without entry with ENTER.	
Comment	A list for entering fixed values is contained in section 9.1.	

FIXED TEXT	Save texts protected against power failure to text memories
	These texts can be assigned, for example as identifications, or also output during printing.
CLEAR ALL TEXTS	Delete all text memories.
LOAD FIXED TEXT	1. Enter memory number of FIXED TEXT No.: 1 20.
	2. Enter text for the selected memory: max. of 20 characters.
	3. To load additional fixed texts, repeat the first two steps.
	4. End entry: Confirm memory number without entry with ENTER.
Comments	Fixed Text No. 20 is displayed during switch-on with a restart, see section 2.1.
	A list for entering fixed values is contained in section 9.3.

DELTA-FIX	Save target weight/tolerance combinations in DeltaTrac memory	
CLEAR ALL DELTA	Delete all DeltaTrac memories.	
LOAD DELTA-FIX	1. Enter memory number of DELTA-FIX No.: 1 25.	
	2. Enter target weight TARG in the displayed unit.	
	3. Enter tolerance TOL in %.	
	4. To enter additional Delta-Fix, repeat the first three steps.	
	5. End entry: Confirm memory number without entry with ENTER.	
Comment	A list for entering fixed values is contained in section 9.2.	

DELTATRAC	Select DeltaTrac application	
FILLING	Weigh in target weight within a tolerance range (factory setting).	
CLASSIFYING	Evaluate the test samples as good, too light or too heavy based on the target weight and tolerance.	
CHECKWEIGHING	Determine difference between target and actual weight.	

LANGUAGE	Select dialog language	
	Possible settings: German, English, French, Dutch, Italian, Spanish	

LAYOUT EXT. KEYBOARD	Select keyboard layout of connected external keyboard	
	Possible setting: Germany, England, France, Holland, Italy, Spain, Scandinavia, Russia, Poland, Belgium, Switzerland, Slovakia, Czech Republic, Latin America, Canada,	

TEXT FOR A B C D	Name identification keys CODE A CODE D	
KEY A	Factory setting: ARTICLE NO.	
KEY B	Factory setting: ORDER NO.	
KEY C	Factory setting: CODE NO.	
KEY D	Factory setting: DOCUMENT NO.	

DATE / TIME	Enter date and time	
EUROPE DATE	Enter DATE in European notation: Day.Month.Year.	
	Enter TIME in European notation: (24) Hours.Minutes.Seconds.	
US DATE	Enter DATE in American notation: Month.Day.Year.	
	Enter TIME in American notation:	
	(12) Hours.Minutes.Seconds. AM/PM,	
	Change over between AM and PM: Press FUNCTION CHANGE key.	
Comments	Enter single-place numbers with a preceding zero.	
Date and time can be printed out.		
	The clock continues to run after the terminal is switched off.	

PERSONAL CODE	Load or delete code for entering the master mode	
CODE	Enter code with a maximum of 8 alphanumeric characters.	
Comment	If no code is entered, access to the master mode is unrestricted.	

SCREEN SAVER	Switch screen saver on or off	
WAITING TIME	Enter time until screen saver is activated. Possible values: 1 99 minutes	
Comment	To hold all display elements at the same luminosity, we recommend not switching off the screen saver.	

BIG WEIGHT DISPLAY	Switch full-display indication of the weight on or off	
	Factory setting: BIG WEIGHT DISPLAY ON	

CONTROL MODE	Adjust control mode	
X 10 KEY	Activation of control mode with X 10 key (factory setting)	
CONTROL MODE ON	This setting is only possible with non-certified scales. The weighing terminal always operates with the higher resolution.	


DYNAMIC WEIGHING	Set printing during dynamic weighing	
NO PRINT	Results during dynamic weighing are not automatically printed out (factory setting).	
AUTO PRINT	Each result during dynamic weighing is automatically printed. Dynamic weights are marked with "Result:" on the printout.	

4.4 SCALE master mode block

In the first block the weighing platform is selected: SCALE 1 ... SCALE 3. The other setting possibilities are the same for all connected weighing platforms.

4.4.1 Overview of the SCALE master mode block

In the SCALE master mode block the following settings for the weight can be carried out:



Legend

- Blocks highlighted in **grey** are described in detail in the following.
- Factory settings are printed in **bold print**.
- Blocks which only appear under certain conditions have a dotted outline.

4.4.2 Settings in the SCALE master mode block

RESET SCALE	Reset weighing platform to factory setting	
	WEIGHING-PROC ADAPT VIBRATION ADAPTER STABILITY DETECTOR AUTOZERO AUTOTARA RESTART	universal weighing average conditions $ASD = 2$ on off off

WEIGHING-PROC ADAPT	Adapt weighing platform to weighing sample
UNIVERSAL WEIGHING	For solid bodies, coarse filling or checkweighing (factory setting).
STATIC WEIGHING	For solid bodies and weighing under extreme conditions, e. g. strong vibrations or weighing animals.
FINE FILLING	For liquid or powdered weighing samples.

VIBRATION ADAPTER	Adapt weighing platform to the vibration influences of the environment
AVERAGE CONDITIONS	Factory setting.
EXTREME CONDITIONS	The weighing platform operates more slowly, however is less sensitive, e. g. suitable with building vibrations and vibrations at the weighing location.
IDEAL CONDITIONS	The weighing platform operates very quickly, however is very sensitive, e.g. suitable with very calm and stabile weighing location.

STABILITY DETECTOR	Adapt automatic stability detector		
	Possible se	Possible settings:	
	ASD = 0	Stability detector sw	ritched off
	(only possible with non-certified weighing platforms)		
	ASD = 1	fast display	good reproducibility
	ASD = 2	A	▼ (factory setting)
	ASD = 3		▼
	ASD = 4	slow display	very good reproducibility

AUTOZERO	Switch automatic zero-point correction on or off		
	The automatic zero-point correction corrects the weight of minor dirt with the weighing platform unloaded. Factory setting: AUTOZERO ON		
Comment	On certified weighing platforms the zero-point correction is always switched on.		

AUTOTARA	Switch automatic taring on or off
	Factory setting: AUTOTARA OFF

RESTART	Switch restart function on or off	
	When RESTART ON is set, the zero point and tare value remain stored after the power supply is interrupted. When the weighing platform is switched on again, the terminal shows the current weight. Factory setting: RESTART OFF	

SECOND UNIT	Select second w	Select second weight unit		
	Possible units: g. Unit Kilogram Pound Ounce	•	Conversion to g = 1000 g ≈ 453.59237 g ≈ 28.349523125 g	
	Troy Ounce Pennyweight Gram	ozt dwt g	≈ 31.1034768 g ≈ 1.555173843 g = 1 g	
Comment	On certified weigh	hing platforms o	only the units permitted by certification appear.	

DISPLAY UPDATE	Set display speed of the weight display
	Select number of updates per second (UPS). Possible values: 6, 10, 15, 20 UPS
Comments	This block only appears when the DISPLAY UPDATE function is supported by the connected weighing platform.
	The possible settings are dependent on the connected weighing platform.

4.5 INTERFACE master mode block

Select the interface connection

→ Select the interface connection in the first block: COM1, COM2, COM3, COM4, COM5 or COM6.

Select interface type

→ Specify the interface type for the selected interface connection COM1 ... COM6.

Possible interface types

• NOT ASSIGNED When the selected interface connection is not assigned.

GA46
 For connection of the GA46/GA46-W printer. An RS232-ID7 interface must be installed on the selected interface connection for this purpose. The other setting possibilities are described in

the operating and installation instructions GA46.

This selection no longer appears when a GA46 printer is already

configured.

• BARCODE For connection of a barcode reader. An RS232-ID7 interface

must be installed on the selected interface connection for this

purpose. For other settings see 4.5.3.

RS232 An RS232-ID7 interface must be installed on the selected

interface connection for this purpose. For other settings see

4.5.2.

ALIBI MEMORY Only for COM2 ... COM6. An Alibi Memory-ID7 must be install-

ed on the selected interface connection for this purpose. No

further settings are required in the master mode.

This selection no longer appears when an Alibi Memory-ID7 is

already configured.

CL20mA Only for COM2 ... COM6. A CL20mA-ID7 interface must be

installed on the interface connection for this purpose.

For other settings see 4.5.2.

RS422 Only for COM5/COM6. An RS422-ID7 interface must be

installed on the interface connection for this purpose.

For other settings see 4.5.2.

• RS485 Only for COM5/COM6. An RS485-ID7 interface must be

installed on the interface connection for this purpose.

For other settings see 4.5.2.

• 4 I/O Only for COM5/COM6. A 4 I/O-ID7 interface with relay box

4-ID7 must be installed on the interface connection for this

purpose. For other settings see 4.5.4.

RELAY BOX 8
 Only for COM6. An RS485-ID7 interface with relay box 8-ID7


must be installed on the interface connection for this purpose.

For other settings see 4.5.4.

ANALOG OUTPUT Only for COM5/COM6 with installed analog output ID7 interface.

Settings in the master mode ID7-Base

4.5.1 Overview of the master mode blocks RS232, RS422, RS485, CL20mA



Legend

- Blocks highlighted in **grey** are described in detail in the following.
- Factory settings are printed in **bold print**.
- Blocks which only appear under certain conditions have a **dotted outline**.

4.5.2 Settings in the master mode blocks RS232, RS422, RS485, CL20mA

RS232, RS422, RS485, CL20MA		
OPERATING MODE	This selection only appears with the RS485 master mode block.	
1:1 CONNECTION	ID7-Base weighing terminal and peripheral are directly connected.	
BUS SLAVE	For operating the ID7-Base weighing terminal in a bus system. The following parameters are set automatically for the dialog: No handshake, no continuous transmission, no transfer string, fixed string framing $C_R L_F$. The PC is the master, the terminals act as slaves and only transmit when requested to do so by the master. The master must also wait until after sending out a command until the slave's answer is received. Each terminal must be assigned a unique address. Additional setting: ENTER TERMINAL ADDRESS. Possible addresses: 1 31	
COMMUNICATION	Set communications parameters.	
STANDARD SETTING	Set communications parameters to factory setting: 7 bits, 2 stop bits, parity even, 2400 baud	
BITS PER CHARACTER	Possible settings: 7 bits, 8 bits	
STOPBITS	Possible settings: 1 stop bit, 2 stop bits	
PARITY	Possible settings: Parity even, parity odd, parity space, parity mark, no parity	
BAUDRATE	Possible settings: 150, 300, 600, 1200, 2400, 4800, 9600, 19200 baud	

RS232, RS422, RS485, CL20MA		
MODE	Set operating mode. This selection does not appear when interface RS485-ID7 is operated in the BUS SLAVE operating mode.	
STANDARD SETTING	Set operating mode to factory setting: CL handshake: no auto transmission (no continuous transmission), transfer string: Standard, string framing: $C_R L_F$	
DIALOG MODE	For dialog between ID7-Base weighing terminal and computer. For other settings see next section.	
PRINT MODE	To print weighing data, e. g. on a form printer. Up to two interfaces can be operated in the print mode. This selection does not appear when two interfaces are already configured in the print mode. For other settings see page 35.	

Set dialog mode

DIALOG MODE	Set dialog between ID7-Base weighing terminal and computer
MMR	For information on dialog mode with the MMR command set, see section 5.1.
HANDSHAKE	Possible settings: • CL HANDSHAKE – for additional information on the CL handshake, see page 34. • XON-XOFF PROTOCOL.
AUTOMATIC CONTINUOUS	This block does not appear with the RS485-ID7 interface. Possible settings:
TRANSMISSION	NO AUTO TRANSMISSION.
	• AUTO SIR — after each measuring cycle a stabilized or dynamic weight is transmitted.
	 AUTO DIR — weight values are transmitted as with AUTO SIR and the special characters in the display are transmitted for a second display. Fixed communications parameters: 9600 baud, 7 data bits, 2 stop bits, parity even
TRANSFER STRING	This block does not appear with the RS485-ID7 interface. Possible settings:
	STANDARD – gross, net, tare
	USER-DEFINED — enter numbers of the application blocks which are to be transmitted or printed out.

Settings in the master mode ID7-Base

DIALOG MODE	Set dialog between ID7-Base weighing terminal and computer	
STRING FRAMING	Possible settings:	
	• <cr><lf> (Factory setting)</lf></cr>	
	• <stx><etx></etx></stx>	
	BLOCK CHECK CHAR	
	• <cr></cr>	
TOLEDO CONTINUOUS	For the continuous transmission of net and tare values to METTLER TOLEDO devices, e. g. to a second display. For a description, see section 5.2. This block does not appear with the RS485-ID7 interface.	
TOLEDO SHORT CONTINUOUS	For the continuous transmission of net values to METTLER TOLEDO devices, e. g. to a second display. For a description, see section 5.2. This block does not appear with the RS485-ID7 interface.	
PE SEND CONTINUOUS	For connecting a PE balance as a reference balance, only with ID7 Count.	

CL handshake

With the CL handshake 3 types of interface control are possible:

Handshake in receiving direction, in transmitting direction and in both directions. After switch-on and after each interruption, the ID7-Base attempts to establish the handshake in both directions.

CL handshake in receiving direction

This type of CL handshake is suitable for data transmission from the ID7-Base to the computer.

- 1. The ID7-Base transmits SYN after switch-on.
- 2. The computer transmits the character ACK after switch-on or after receiving SYN.
- 3. ID7-Base then sends the response to a command or to a key actuation after each ACK.

CL handshake in transmission direction

This type of CL handshake is suitable for data transmission from the computer to the ID7-Base.

- 1. The ID7-Base transmits SYN after switch-on.
- 2. The computer transmits the character SYN after switch-on or after receiving SYN.
- 3. ID7-Base acknowledges the receipt of SYN again with SYN and signals its readiness to receive with ACK.
- 4. Then the computer can transmit a command after each ACK.

CL handshake in both directions

- 1. The ID7-Base transmits SYN after switch-on.
- 2. The computer transmits the character SYN after switch-on or after receiving SYN.
- 3. ID7-Base acknowledges the receipt of SYN again with SYN and signals its readiness to receive with ACK.
- 4. The computer signals its readiness to receive with ACK.
- 5. During operation the ID7-Base receives data and transmits ACK when it is ready to receive data again.

The computer receives data and transmits ACK when it is ready to receive data again.

Set print mode

PRINT MODE	Configure printout on an exte	rnal printer		
HANDSHAKE	Possible settings:			
	NO HANDSHAKE			
	CL HANDSHAKE			
	XON-XOFF PROTOCOL			
LINE LENGTH	Enter number of characters per			
	Possible settings: Factory setting:	1 80 characters 40 characters		
LINE FRAMING	Enter ASCII character for line fro	mina		
LIVE TIVIMITO	Possible settings:	ASCII 0 255		
	Factory setting:	ASCII 013 010 (C _R L _F)		
CONFIGURATION PRINTOUTS	Configuration of printouts assigned to the individual keys. The current configuration for each offered key can be printed out with CHANGE CONFIGURATION, EDIT, PRINT.			
TRANSFER KEY	For each selected key the printe	out can be configured as follows:		
CODE A KEY	DELETE ALL			
	STANDARD SETTING	key-specific		
CODE D KEY	CHANGE CONFIGURATION	see below		
DYNAMIC KEY				
Pac keys				
AUTOMATIC PRINT-OUT	(ENTER key) is automatically p To activate this function in the	N is selected, the key configuration of the transfer key crinted out for each weight change > 10 d. weighing mode, press the ENTER key once, then a cally each time the weight changes.		

Change configuration

If CHANGE CONFIGURATION is selected for a key, the function keys change to the following assignment with which the data string can be displayed and edited:

<<	<	EDIT	\uparrow	>	>>
Display first block in data string	Display previous block in data string	Edit data string, trigger test printout, see page 37	Exit level and return to higher-level block; end configuration	Display next block in data string	Display last block in data string

Example

→ To display the next block in the data string, press the > key.

Display data string

After selecting CHANGE CONFIGURATION the first block of the configured data string appears.

Possible displays

BLOCK XXX Application block

• SPECIAL FUNCTION Separator line -----

• SPECIAL FUNCTION Separator line ******

• SPECIAL FUNCTION Separator line ++++++

+++++++

SPECIAL FUNCTION Blank line

BLANK LINE

* * * * * * *

• SPECIAL FUNCTION Paper advance

ADVANCE


• SPECIAL CHARACTERS ASCII characters; NN = Number of characters;

 $NN \times XXX$ XXX = Decimal representation of the ASCII character

BUFFER END appears for last block of the configured data string

The position of the displayed block in the total data string is shown in the lower left corner of the display.

- 1 the displayed block is the first block of the data string
- 2 the displayed block is approximately in the middle of the data string
- 3 the displayed block is the last block of the data string



Edit data string

If EDIT is selected, the function keys change to the following assignment with which the data string can be edited:

DEL	PRINT	INS	\uparrow		
Remove displayed block from the data string	Trigger test printout	Insert block in the data string, see page 37	Exit level and return to the higher-level block	_	_

Insert block

After pressing INS the function keys are assigned the normal assignment for the master mode again.

INS	Insert block in the data string before the last position shown
BLANK LINE	Insert a blank line in the data string.
SEPARATOR LINE	Insert separator line in the data string. Possible separator lines:, * * * * * * * * * , + + + + + + + + +
APPLICATION BLOCKS	Insert application block in the data string.
BLOCK 000/00	Enter block no. and sub-block no. If all sub-blocks are to be inserted, enter sub-block no. 0.
WITH TEXT	Print out designation of application block.
WITH LEADING BLANK SPACES	Print weights with leading blank spaces.
EXTRABLANK SPACES	Enter number of additional blank spaces between designation and value.
SPECIAL CHARACTERS	Insert ASCII characters in the data string.
CHARACTER 000 NUMBER 00	Enter ASCII character in decimal representation. Enter number of characters.

End configuration

→ Press ↑ key, several times if necessary, until the Yes/No inquiry PAPER ADVANCE and/or SAVE CHANGES appears or until the configured key is displayed again.

Notes

- The PAPER ADVANCE inquiry only appears when no advance has been defined yet.
- The SAVE CHANGES inquiry only appears when the configuration has actually been changed.

Settings in the master mode ID7-Base

4.5.3 Set barcode reader

BARCODE	Set barcode reader
TYPE	
DL900 LS3603 	Select barcode reader. When one of the barcode readers is selected, the communications and mode parameters for the selected barcode reader are automatically set.
OTHER	For other barcode readers: Settings in the sub-blocks COMMUNICATION and MODE as for the blocks RS232/RS422/RS485/CL, see section 4.5.2. The PRINT MODE setting is not possible when using barcode readers!
DESTINATION BLOCK 000/00	Enter the number of the application block and of the subsequent block with which the barcode entry is to be described. When a target block is selected, barcode information can be read directly into this block without having to press a key beforehand, see section 3.13.2.

4.5.4 Configure inputs/outputs

4 I/O / RELAY BOX 8	
INPUT	Operate inputs internally or externally.
INTERNALLY	Factory setting.
EXTERNALLY	Inputs are independent of the weighing functions. Read status of the inputs with the AR707 command, see section 6.3.2.
OUTPUT	Operate outputs internally or externally.
INTERNALLY	Factory setting.
EXTERNALLY	Outputs are independent of the weighing functions. Set the outputs via the AW706 command, see section 6.3.2.

Assignment of inputs/outputs by ID7-Base

Output signals

Output 1	TOO LITTLE	for DeltaTrac application
		FILLING, CHECKWEIGHING
	01.400.7	•
	CLASS 1	for DeltaTrac application CLASSIFYING
Output 2	OKAY	for DeltaTrac application
'		FILLING, CHECKWEIGHING
		•
	CLASS 2	for DeltaTrac application CLASSIFYING
Output 3	TOO MUCH	for DeltaTrac application
'		FILLING, CHECKWEIGHING
		•
	CLASS 3	for DeltaTrac application CLASSIFIYING
Output 4	Stability of v	veighing platform

Input signals

Input 1	ON/OFF key
Input 2	Set weighing platform to zero
Input 3	Tare weighing platform
Input 4	ENTER key

Interface description ID7-Base

5 Interface description

To exchange data with a computer, the ID7-Base weighing terminal is equipped with an RS232 interface. Up to 5 additional interfaces are available as an option.

The interfaces operate independently of each other, can be used simultaneously and can be adjusted individually, see section 4.5.

To operate the serial interfaces in the **dialog mode**, one of the following METTLER TOLEDO command sets must be selected in the master mode:

- MMR command set, see section 5.1.
- METTLER TOLEDO Continuous mode, see section 5.2.

5.1 MMR command set

5.1.1 Syntax and formats of communication

Commands and responses for transmitting weights have the following formats:

Command format

Identification	_	Weight value	_	Unit	Framing
Character sequence for specification of command (1 4 characters)		1 8 digits, number of digits variable		1 3 characters, number of characters variable	Definable in master mode, factory setting: C _R L _F

Response format

Identification	_	Weight value	_	Unit	Framing
Character sequence for specification of response (2 3 characters)		10 digits, right- justified, filled out with blank spaces		3 characters, left-justified, filled out with blank spaces	definable in master mode, factory setting: $C_{\text{R}}L_{\text{F}}$

Example

Command Tare specification Response Tare specification

T_1	3 2 .	9,5_	k g		
$T_{\perp}B_{\perp}H$		1	3	2 9 5	_ k g

ID7-Base Interface description

Data formats

• The following symbols are used in the following command description:

Weight value 10 characters with sign and decimal point, right-justified

(with preceding blank spaces)

Unit 3 characters, left-justified (with following blank spaces)

Text_n maximum of n characters, left-justified

 The string framing is mandatory, however it is **not** contained in the following command description!

• Enter commands as ASCII characters. The following ASCII characters are available: 20 hex/32 deci ... 7F hex/127 deci, see section 9.4.

BUS SLAVE operating mode (RS485)

In the BUS SLAVE operating mode each command and each response begins with a code for the terminal address.

Terminal address 1 ... 9 Code "1" ... "9" (31H ... 39H)
Terminal address 10 ... 31 Code "a" ... "v" (61H ... 76H)

Example Command to terminal 3: 3 S

Interface description ID7-Base

5.1.2 Command overview

Command	Meaning	Page
R0 / R1	Switch keypad on/off	43
Z	Set weight display to zero after weighing platform stabilization	43
U	Change over terminal to a different weight unit	43
Т	Tare	44
T	Specify tare weight	44
DY	Specify DeltaTrac target value	45
S	Transmit in case of weighing platform stabilization	45
SI	Transmit independent of weighing platform stabilization	45
SIR	Transmit repeatedly independent of weighing platform stabilization	46
SR	Transmit stabilized weight values repeatedly depending on a weight change	46
SR	Transmit repeatedly depending on weighing platform stabilization with specification of an excursion value	46
SX	Transmit data record after weighing platform stabilization	47
SXI	Transmit data record independent of weighing platform stabilization	47
SXIR	Transmit data record repeatedly independent of weighing platform stabilization	47
ARNo.	Read information of application block	48
AWNo	Write to application block	48
D	Write to display	48
P	Print alphanumeric characters or barcodes on the GA46	48,49
DS	Trigger acoustic signal	49
ID	Interrogate terminal identification	49
W	Actuating digital outputs	50

ID7-Base Interface description

5.1.3 Command description

Switch keypad on or off

Command	$egin{array}{cccccccccccccccccccccccccccccccccccc$	
Response	R_B Keypad switched on or off	
Comments	 Factory setting: Keypad switched on. When the keypad is switched off, the terminal cannot be operated manually. 	

Set zero

Command	Set gross weight display to zero after weighing platform stabilization, effect as when ZERO-SET key is pressed.	
Response	Z_B Weighing platform set to zero Z Command cannot be executed: Zero-set range dropped below Z_+ Command cannot be executed: Zero-set range exceeded	
Comments	Setting to zero is not possible when the weighing platform stabilizes in the zero- set range.	
	With some weighing platform types setting to zero deletes a saved tare weight. This is indicated with the message TA, see section 5.1.4.	

Changing over to different weight unit

Command	Change over weight display to different weight unit Change over weight display to first weight unit	
Response	U_B Weight display changed over to different weight unit	
Comment	Possible units: g, kg, ozt, oz, dwt	

Interface description ID7-Base

Tare

Command	Tare weighing platform: After the weighing platform stabilizes, the current weight value is saved as the tare weight and the weight display is set to zero with the weight placed on the platform. Effect as when TARE key is pressed. Tare weight (weight value) Unit Specify tare weight: The content of the tare memory is overwritten with the specified tare weight and the net weight is displayed. Effect as when TARE ENTRY, 0 9, ENTER key sequence is pressed. Delete tare weight.
Response	T_B Tare weight (weight value) Unit Weighing platform is tared T_B_H Tare weight (weight value) Unit Weighing platform is tared with specified weight T Command cannot be executed: Tare range dropped below T_+ Command cannot be executed: Tare range exceeded
Comments	 Taring is only possible when the weighing platform stabilizes within the tare range. The tare weight is always transmitted in the first weight unit. Each taring command overwrites the content of the tare memory with the new tare weight. Taring with an unloaded weighing platform deletes the tare memory. On some weighing platform types a zero set is carried out in the unloaded state. This is displayed with the message ZA, see section 5.1.4. On not certified weighing systems the tare weight is automatically rounded to the current increment. On certified weighing systems: Tare range for MultiRange only in first increment range.
Example	Command: T Response: T_B1_1_26_5_0 _ k_g

ID7-Base Interface description

Specify DeltaTrac target value

Command	D_Y _ Target weight (weight value) _ Unit _ Tolerance _ % Specify DeltaTrac target value D_Y Delete DeltaTrac target value	
Response	D_B DeltaTrac target value loaded/deleted	
Comment	Watch limits, see section 3.1.1	
Example	Command: D_Y _ 45 _ k_g _ 5 _ % Response: D_B	

Transmit content of display

Command	Transmit a stabilized weight when weighing platform is stabilized. Transmit a stabilized or dynamic weight independent of weighing platform stabilization.
Response	S Weight value _ Unit Stabilized weight value transmitted S_D _ Weight value _ Unit Dynamic weight value transmitted S_I Invalid weight S_I - Weighing platform in underload range S_I - Weighing platform in overload range

Interface description ID7-Base

Transmit content of display repeatedly

Command	Transmit stabilized or dynamic weight values after each measuring cycle independent of weighing platform stabilization. Transmit the next stabilized weight value after a weight change (e. g. different item) and one dynamic and the next stabilized weight value after each deflection > 30 d.	
	Transmit the next stabilized weight value and, depending on the specified deflection, a dynamic weight value after a weight change greater than the specified deflection value.	
Response	S Weight value _ Unit Transmit stabilized weight value repeatedly S_D _ Weight value _ Unit Transmit dynamic weight value repeatedly	
Comment	Stop command with S, S,I command or by interrupting the interface	
Example	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	

ID7-Base Interface description

Transmit data record

Command	Transmit a data record with stabilized weight values after weighing platform stabilization. Effect as if ENTER key is pressed. Transmit a data record with stabilized or dynamic weight values independent of weighing platform stabilization. Transmit data records with stabilized or dynamic weight values repeatedly independent of weighing platform stabilization.
Response	S_X Application block Application block] A No Data record Data record with stabilized weight values transmitted S_X_D _ Application block Application block] A No Data record Data record with dynamic weight values transmitted
	$\begin{array}{cccccccccccccccccccccccccccccccccccc$
Comments	 Number of application block: three-digit with leading zeros. The content of the corresponding application block is contained in data record, see chapter 6. Standard data record consists of 3 blocks: S_X = A_0_1_1_1 = Gross weight (weight value) = Unit = A_0_1_1_3 = Tare weight (weight value) = Unit A_0_1_1_3 = Tare weight (weight value) = Unit The continuous transmission of data records started with the S_X_I_I_R command can be stopped with the S_X or S_X_I command.
Example	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$

Interface description ID7-Base

Read application block

Command	A R No.	Read content of application block
Response	A B Information	Content of application block transmitted
Comments	 Transmitted information is dependent on application block, see chapter 6. Number of application block must be entered as 3 digits with preceding zeros. 	

Write to application block

Command	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	Written to application block Reset application block Delete application block
Response	$A_{\perp}B$	Written to application block
Comments	 Information to be entered is dependent on target block, see chapter 6. Deleting and resetting have same effect. 	

Write to display

Command	DText_20 Write to display Switch display to dark D Set display to normal status
Response	D_B Written to display
Comments	 Character stock: ASCII characters 20 hex/32 deci 7F hex/127 deci, see section 9.4. Watch capitalization.

Alphanumeric printout on GA46 printer

Command	P _ Text_20 Print text as per setting P _ \$! 1 Text_20 Print text in small type P _ \$! 2 Text_20 Print text in normal type P _ \$! 3 Text_20 Print text in large type P _ P _ \$! 1 Text_20 Print text in large type P _ \$! 2 Text_20 Print text in large type P _ P _ \$! 3 Text_20 Print text in large type
Response	P_B Alphanumeric characters printed
Comments	 Character stock: ASCII characters 20 hex/32 deci 7F hex/127 deci, see section 9.4. Test is printed in last selected type size. Watch capitalization.

ID7-Base Interface description

Barcode printout on GA46 printer

Command	P _ \$ # 1 Text_20, barcode-specific P _ \$ # 2 Text_8, barcode-specific P _ \$ # 3 Text_13, barcode-specific P _ \$ # 4 Text_20, barcode-specific P _ \$ # 5 Text_20, barcode-specific P _ \$ # 6 Text_20, barcode-specific P _ \$ # 6 Text_20, barcode-specific	Print Code 39 Print EAN 8 Print EAN 13 Print EAN 128 Print Code 2 of 5 Print Code 2 of 5 interleaved Print blank line		
Response	$P_{\perp}B$	Barcode printed		
Comments	 Character stock: ASCII characters 20 hex/32 deci 7F hex/127 deci, see section 9.4. With Code 39, 3 barcodes can be printed next to each other. Separating characters: \$\$ or H_T (ASCII character 09 hex/9 deci). Arrangement of barcodes: Barcode 2, Barcode 1, Barcode 3. 			

Acoustic signal

Command	$D_{\downarrow}S$	Generate short acoustic signal (beep tone) in terminal
Response	$D_{\perp}B$	Acoustic signal generated in terminal

Identification

Command	Interrogate identification of terminal
Response	I_D_7 _ Program number of Pac

Interface description ID7-Base

Actuating digital outputs

Command	WStatus Switch individual digital outputs on or off WStatus 1Time 1Status 2Time 2 Status 4Time 4Status 5 Trigger time sequence of status changes of digital outputs Reset all outputs to logical 0 Status: Each output is assigned a value. The total of the values of those outputs which are to be closed is indicated as the "Status". Digital output 1
Response	W_B Digital outputs set
Comments	 Max. 5 statuses "Status" and 4 intervals "Time" are possible. After sequence has been run, digital outputs freeze in last status "Status". A break in the port has no effect on the outputs. If terminal receives a new W command before time sequence has been run, ongoing sequence will be aborted immediately. If limits for "Status" and "Time" are not adhered to, error message EL appears.
Example	Command: W_5 Digital outputs 1 and 3 are closed, all others opened Command: W_1_1_1_0,0,0_3,2_5,0,0,0_3,3_5,0,0_0 triggers following sequence: Output 1 Output 6 Output 6

ID7-Base Interface description

5.1.4 Terminal messages – only with RS232, RS422 or CL

In the dialog mode the ID7-Base weighing terminal transmits an acknowledgement to the computer each time a key is pressed.

When this pressing of a key is replaced with an interface command, the acknowledgement only differs in the second character in the response format which is part of the command:

Function	Key	Acknowledgement
Set zero		$Z_{\perp}A$
Tare		$T_{\perp}A$
Specify tare weight		T_A_H (see command T)
Change over unit		$U_{\perp}A$
Transmit data record in case of weighing platform stabilization		$\boxed{\mathbb{S}_{\perp}\mathbb{T}_{\perp}}$ (see command SX)
Switch over weighing platform		n = weighing platform 1 3
Dynamic weighing		[A A 0 1 6 _ Weight value _ Unit
Identification A D	A D	
Function keys	F1 F6	KF_x X = I, J, K, L, M, N

5.1.5 Fault messages

Fault messages always consist of 2 characters and a string frame. The string frame can be defined in the master mode (section 4.5.2).

$\boxed{\mathbb{E}_{\perp} \mathbb{T}}$ Transmission error

The terminal transmits a transmission error for errors in the received bit sequence, e. g. parity errors, missing stop bit.

E_S Syntax error

The terminal transmits a syntax error when the received characters cannot be processed, e. g. command does not exist.

E,L Logic error

The terminal transmits a logic error when a command cannot be executed, e. g. when an attempt is made to write to a write-protected application block.

Interface description ID7-Base

5.2 METTLER TOLEDO continuous mode

These operating modes are suitable for continuous data transmission in real time to METTLER TOLEDO devices, e. g. to a second display.

The data are even transmitted when the weighing platform is moving or the gross weight = 0.

There are 2 different continuous modes:

SB2

- Continuous mode net and tare values are continuously transmitted.
- Short continuous mode only net values are continuously transmitted.

DF1

Output format

Weight values are always transmitted in the following format:

SB3

STX	ASCII characters 02 hex/2 deci, character for "start of text"
	is required by some printers
SB	For status bytes, see below
DF1	Data field with 6 digits for the weight value transmitted without a
	decimal point and unit
DF2	Data field with 6 digits for the tare weight:

DF2

CR

CHK

is not transmitted in the short continuous mode

CR Carriage return (ASCII character OD hex/13 deci)

Checkey (2) part complement of binary sum

CHK Checksum (2-part complement of binary sum of 7 lower bits of all previously transmitted characters, including STX and CR)

Status byte SB1

STX

SB1

Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
0	1	Rounding / Increment		De	ecimal positi	on

Bit 4	Bit 3	Rounding/ Increment
0	1	1
1	0	2
1	1	5

Bit 2	Bit 1	Bit 0	Decimal position
0	0	0	XXXX00
0	0	1	XXXXXO
0	1	0	XXXXXX
0	1	1	XXXXX.X
1	0	0	XXXX.XX
1	0	1	XXX.XXX
1	1	0	XX.XXX
1	1	1	X.XXXXX

ID7-Base Interface description

Status byte SB2

Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
0	1	O lb	0 Stabiliza- tion	O Normal status	O Positive sign	O Gross value
				1 Underload/ overload	1 Negative sign	1 Net value

Status byte SB3

Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
0	1	0	O Basic state 1 Print request	V	/eight valu	ie

Bit 2	Bit 1	Bit 0	Weight value
0	0	0	kg / lb (SB2 Bit 4)
0	0	1	g
0	1	0	t
0	1	1	OZ
1	0	0	ozt
1	0	1	dwt
1	1	0	ton
1	1	1	free unit

Application blocks ID7-Base

6 Application blocks

Application blocks are internal information memories in which weighing data, calculated quantities, configuration data or character sequences entered with the keypad are stored. The content of the application blocks can be read out or written to with a computer.

When the GA46 printer is connected, the assignment of the application blocks can be printed out, see operating instructions for the GA46 printer.

6.1 Syntax and formats

6.1.1 Read application block

Read $A_R N_0$. The weighing terminal receives the command from the com-

puter to read out the content of the "No." application block.

This command is **not** contained in the following description of

the application blocks.

Response As a response the weighing terminal transmits the content of

the "No." application block to the computer.

This response is contained in the following description of the

application blocks.

Example Command $A_R O_2 1$ Read out tare memory 1.

Response [A_B]_____1_1_0_...5 [_k_g__]

Note

If an application block is not in use, the weighing terminal transmits the corresponding number of blank spaces in place of the data.

For example, when Tare Memory 1 is not in use, the weighing terminal transmits the following response: $A_B = A_B = A_B$

6.1.2 Write to application block

Write AWNo. Information The weighing terminal receives the command from the

computer to write to the "No." application block.

This command is contained in the following description of

the application blocks.

Response A_B The weighing terminal transmits a confirmation to the

computer.

This response is **not** contained in the following description

of the application blocks.

Example Write $A_W 0_2_1 - 1_2_1 - 1_2_1 - 1_2_1 - 1_2_1 - 1_1_2 -$

Write to tare memory 1.

Response A_B

ID7-Base Application blocks

Notes

 Only those application blocks can be written to for which the corresponding AW command is listed in the following description.

- An application block can consist of one or more sub-blocks, and the numbering of the sub-blocks begins with 1.
- The sub-blocks of an application block can each contain a maximum of 20 characters.
- The sub-blocks are separated with \$\$ or H_T (ASCII character 09 hex/9 deci): $A_W No. _ Sub-block 1 $_$$ Sub-block 2 $_$$... Sub-block n$
- Extensive application blocks are displayed so that each sub-block begins in a new line.

6.1.3 Data formats

• In the following description of the application blocks the following data formats are used:

Weight value10 digits with sign and decimal point, right-justified
(with preceding blank space)Unit3 characters, left-justified (with following blank spaces)Number_nNumber, n digits, right-justified (with preceding blank spaces)Text_nmaximum of n characters

• Conclude commands and responses with the string frame $C_R L_F$ (ASCII characters $C_R = 0D$ hex/13 deci, $L_F = 0A$ hex/10 deci). The string frame is **not** contained in the following description.

Application blocks ID7-Base

6.2 TERMINAL, SCALE application blocks

No.	Content	Format		
001	Terminal type	Response:	[A ₁ B _ M ₁ e ₁ t ₁ t ₁ t ₁ e ₁ r ₁ - ₁ T ₁ o ₁ 1 ₁ e ₁ d ₁ o ₁₋₁ I ₁ D ₁ 7]	
002	Program number	Response:	[A,B]_]I,T,0,7,-,0,-,0,x,x,x _	
006	Transfer key	Response: Write:	[A ₁ B Keys 2 ₁ 4] [A ₁ W ₀ 0 ₁ 0 ₁ 6 \$ \$ 2 ₁ 4	
007	Current gross weight (2nd weight unit)	Response:	A_BWeight value Unit	
800	Current net weight (2nd weight unit)	Response:	A_BWeight value Unit	
009	Current tare weight (2nd weight unit)	Response: Write:	A_B _ Weight value _ Unit A_W O_O_9 _ Weight value _ Unit	
010	Current weighing platform	Response: Write:	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	
011	Current gross weight (1st weight unit)	Response:	A_BWeight value Unit	
012	Current net weight (1st weight unit)	Response:	9: A_BWeight value Unit	
013	Current tare weight (1st weight unit)	Response: Write:		
014	Content of display	Response:	e: ABDDisplay Display = Text_20 or weight value	
015	Date	Response: Write:	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	
016	Dynamic weighing	Response: Write: Comment:	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	
018	Difference target/actual weight	Response:	A_BWeight value Unit	
019	Date and time	Response:	[A,B] D, D, / _ M, M, / _ Y, Y	
		Write:	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	

ID7-Base Application blocks

No.	Content	Format		
020	Current DeltaTrac	Response: Write:	A_B _ Target weight (weight value) _ Unit Tolerance value (number_2) _ \% A_W O_2_O _ Target weight (weight value) _ Unit \\$ \$ Tolerance value (number_2) _ \%	
021 045	Tare memory 1 25	Response: Write: Comment:	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	
046 070	DeltaTrac memory 1 25	Response: Write: Comment:	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	
071 090	Text memory 1 20	Response: Write: Comment:	$A_B = Text_20$ $A_W = Text_20$ $A_W = 71 \dots 90$	
091	Barcode EAN 28, EAN 128	Response: EAN 28: EAN 128 01:	A_B _ EAN 28 _ EAN 128 01 _ EAN 128 310 _ EAN 128 330 2_8 Article Check digit Weight Article:	
			Check digit: 1-digit, calculated by ID7-Base Length: total of max. 16 digits \[\begin{array}{cccccccccccccccccccccccccccccccccccc	

Application blocks ID7-Base

No.	Content	Format	
092	Barcode EAN 29	Response: Comment:	Article: 4-digit article no. from memory Code A Check digit: 1-digit no., calculated from ID7-Base for the weight Weight: 5-digit positive weight value with 3 places to right of point between 00.000 kg 99.999 kg
093	Barcode EAN 29 A	Response: Comment:	Article: 5-digit article no. from memory Code A Weight: 5-digit positive weight value with 3 places to right of point between 00.000 kg 99.999 kg
094 097	Identification data Code A Code D	Response: Write: Comment:	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$
098	Number of last Alibi entry	Response: Note:	[A_B Number_6] The data record number is output with leading zeros

ID7-Base Application blocks

6.3 INTERFACE application blocks

Application blocks are reserved for the possible interface connections. These application blocks can only be read and written to when an ...-ID7 interface is actually installed on the interface connection concerned.

6.3.1 Serial interfaces

No.	Content	Format	
101	Description of application	Response:	[A,B]_ ID7 Interfaces
102	Program designation	Response:	[A,B _ IK07-0-0100]
103	Transmit buffer COM1	Response: Write*:	[A_B _ Transmit buffer COM1] [A_W 1_0_3 _ Information]
104	Transmit buffer COM2	Response: Write*:	A_B _ Transmit buffer COM2 A_W 1_0_4 _ Information
201	Description of application	Response:	[A,B]_ ID7 Interfaces]
202	Program designation	Response:	[A,B]_ IK07-0-0100]
203	Transmit buffer COM3	Response: Write*:	A B Transmit buffer COM3 A W 2 O 3 Information
204	Transmit buffer COM4	Response: Write*:	[A_B]_ Transmit buffer COM4] [A_W 2_0_4 _ Information]
701	Description of application	Response:	[A,B]_ ID7 Interfaces]
702	Program designation	Response:	[A,B _ IK07-0-0100]
703	Transmit buffer COM5	Response: Write*:	[A_B _ Transmit buffer COM5] [A_W 7_0_3 _ Information]
704	Transmit buffer COM6	Response: Write*:	[A_B]_ Transmit buffer COM6] [A_W 7_0_4 _ Information]

* Comments on the transmit buffers

- The entered information is transmitted directly via the selected interface.
- A transmit buffer contains a maximum of 256 characters.

Application blocks ID7-Base

6.3.2 Digital inputs/outputs

The following application blocks are only available when interface 4 I/O-ID7 is installed on COM5/COM6 or interface RS485-ID7 and relay box 8-ID7 is installed on COM6.

When the weighing terminal checks the outputs, the blocks concerned cannot be written to, and the $\lceil E \rceil L \rceil$ error message appears.

No.	Content	Format	
706	Digital outputs 1 COM5/COM6	Response: Write:	A B B 8-place binary value * A W 7 O 6 S Place binary value *
707	Digital inputs 1 COM5/COM6	Response:	A B B 8-place binary value *
708	Dig. outputs 2 COM6	Response: Write:	A_B _ 8-place binary value * A_W 7_0_8 _ 8-place binary value *
709	Dig. inputs 2 COM6	Response:	A_B8-place binary value *
710	Dig. outputs 3 COM6	Response: Write:	A_B _ 8-place binary value * A_W 7_1_0 _ 8-place binary value *
711	Dig. inputs 3 COM6	Response:	A_B _ 8-place binary value *
712	Dig. outputs 4 COM6	Response: Write:	A_B8-place binary value * A_W 7_1_2 _ 8-place binary value *
713	Dig. inputs 4 COM6	Response:	A_B 8-place binary value *
714	Dig. outputs 5 COM6	Response: Write:	A_B _ 8-place binary value * A_W 7_1_4 _ 8-place binary value *
715	Dig. inputs 5 COM6	Response:	A_B _ 8-place binary value *
716	Dig. outputs 6 COM6	Response: Write:	A_B8-place binary value * A_W 7_1_6_8-place binary value *
717	Dig. inputs 6 COM6	Response:	A_B _ 8-place binary value *
718	Dig. outputs 7 COM6	Response: Write:	A B B 8-place binary value * A W 7 1 8 8-place binary value *
719	Dig. inputs 7 COM6	Response:	A_B _ 8-place binary value *
720	Dig. outputs 8 COM6	Response: Write:	A_B8-place binary value * A_W 7_2_0 _ 8-place binary value *
721	Dig. inputs 8 COM6	Response:	A B B 8-place binary value *

^{* 8-}place binary value: Bit8, Bit7 ... Bit1 Bit8 = output/input 8 ... Bit1 = output/input 1

ID7-Base What to do if ...?

7 What to do if ...?

Error / Display	Possible causes	Remedy
Display is dark	No mains voltage Terminal switched off	→ Check mains→ Switch on terminal
	Power cord not connected	→ Plug in power plug
	Brief malfunction	→ Switch terminal off and on again
Underload	Load plate not in place	→ Apply load plate
	Preload not applied	→ Apply preload
	Weighing range dropped below	→ Set zero
Overload	Weighing range exceeded	→ Relieve weighing platform
	Weighing platform locked	→ Release lock
Weight display unstable	Agitated set-up location	→ Adjust vibration adapter
	Draft	→ Avoid drafts
	Agitated weighing sample	→ Weigh dynamically
	 Contact between load plate and/or weighing sample and surroundings 	→ Eliminate contact
	Power malfunction	→ Check mains
Wrong weight display	Wrong setting to zero of weighing platform	→ Relieve weighing platform, set to zero and repeat weighing
	Wrong tare weight	→ Delete tare or enter right tare value
	Contact between load plate and/or weighing sample and surroundings	→ Eliminate contact
	Weighing platform tilted	→ Level weighing platform
	Wrong weighing platform selected	→ Select right weighing platform
PLUG IN	Weighing platform cable not plugged in	→ Switch off terminal, plug in weighing platform cable and switch on terminal again
		→ If the message appears again: contact METTLER TOLEDO Customer Service
IDENTCODE =	Test cycle started	→ Complete test by pressing the ZERO-SET key
WRONG CODE	Wrong personal code	→ Enter right personal code

What to do if ...?

Error / Display	Possible causes	Remedy
SCALE NO. ERROR	Error in weighing cell	→ Repeat test
		→ If the message appears again: contact METTLER TOLEDO Customer Service
OUT OF RANGE	Zero set range exceeded	→ Relieve weighing platform
	Gross weight negative	→ Relieve weighing platform and set to zero
	Taring range exceeded	→ Relieve weighing platform and set to zero
	 Entered value outside permissible range 	→ Enter permissible value
NOT ALLOWED	Wrong cycle time for dynamic weighing	→ Enter cycle time between 1 and 255 cycles
	Weighing platform does not exist	→ Connect weighing platform
	Print with negative weight value	→ Relieve weighing platform, set to zero and repeat weighing
NOT EXISTENT	Recalled memory not assigned	→ Recall other memory
NO DATA TRANSFER	Weighing platform does not transmit	→ Switch terminal off and on again
	data to the terminal	→ If the message appears again: contact METTLER TOLEDO Customer Service
INTERF. COM X – BREAK	Break in receiving cable of specified	→ Check cable and connectors
	interface	→ Check external devices (on/off)
TRANSMIT BUFFER FULL	No transmission	→ Check handshake
	 Too many key messages and baud rate too low 	→ Increase baud rate
KEY BUFFER FULL	Data string currently being edited contains too many blocks	→ Remove blocks from data string
ERROR BARCODE	The specified application block contains no data	→ Select application block which contains data
	 Wrong sub-block selected, e.g. sub- block 0 	→ Select permissible sub-block
NO BLOCK	Entered application block does not exist	→ Enter different application block
BUFFER IS FULL	Data string of transfer key contains more than 10 application blocks	→ Change configuration of transfer key

ID7-Base What to do if ...?

Error / Display Possible causes		Remedy	
DISPLAY MODE	Weighing cell defective	→ Contact METTLER TOLEDO Customer Service	
	• 2 weighing platforms with same scale number connected	→ Contact METTLER TOLEDO Customer Service	

Technical data and accessories ID7-Base

8 Technical data and accessories

8.1 Technical data


Terminal			
Display	 Active, brightly lit green VFD dot matrix display, with graphics capabilities, 40 x 170 pixels, display field 135 x 46 mm BIG WEIGHT DISPLAY with 35 mm high characters Cover of scratch-resistant, hardened, antireflection glass 		
Keypad	 Tactile-touch membrane keypad with acoustic acknowledgement Scratch-resistant marking, 3-color 4 keys A to D for identification data, 6 function keys with function change and info key, 4 scale function keys, numerical keypad Alphanumeric input possible with function keys Standard connection for external MFII keypad 		
Housing	 All nickel chromium steel DIN X5 CrNi 1810 Weight: net 3.5 kg; gross 5 kg 		
Protection type (IEC 529, DIN 40050)	 Dust and water-tight as per IP68 Resistant to high-pressure and steam jet cleaning as per IPX9K 		
Power supply	 100 V – 240 V, +10/–15 %; 50/60 Hz Power cord with grounded plug, length approx. 2.5 m Power consumption approx. 60 VA 		
Ambient conditions as per EN 60950	 Pollution degree 2 Overvoltage category II Maximum operating elevation in m above sea level: 2000 m 		
Ambient temperature	Operation: -10 - +40 °C for weighing platforms of certification class III 0 - +40 °C for weighing platforms of certification class II Storage: -25 - +60 °C		
Relative humidity	20 – 80 %, non-condensing		
Weighing platform connection	 1 IDNet connection standard for METTLER TOLEDO weighing platforms of the series D, F, K, N, Spider ID, DigiTOL, analog scales with AWU 3/6 and analysis and precision scales of the series B, G and R 2 IDNet additional connections possible or 1 analog and 1 IDNet connection 		
Interface connection	1 RS232 connection standard, maximum of 5 additional interface connections possible		
Total load of all output voltages on the ID7- Base	Output voltage 5 V max. 600 mA Output voltage 12 V max. 200 mA Output voltage 24 V max. 100 mA		


Weighing functions		
Tare compensation	At the press of a button or automatically, up to maximum load (subtractive)	
Tare target value	For single-range scales over entire weighing range (subtractive)	
	For multi-range scales depending on national calibration regulations	
	25 stored tare memories, protected against power failure	
Tare calculation	Tare addition, tare multiplication, sub-tare	
Tare indicator	NET lights up with saved tare weight	
DeltaTrac	Analog display of dynamic measured values	
	With optical marks for target value and tolerances	
	3 selectable applications	
	25 DeltaTrac memories, protected against power failure	
Setting to zero	Automatic or manual	
Gross changeover	Display of weight value can be changed over to gross weight at press of a button	
Unit changeover	Unit can be changed over to weight units kg, g, lb, oz, ozt, dwt in dependence or national calibration regulations at press of a button	
Dynamic weighing	Cycle time adjustable from 1 – 255 cycles	
	Automatic printout selectable	
Stabilization detector	4-step, with motion indicator	
Weighing process adapter	3-step adjustment to weighing sample	
Vibration adapter	3-step adjustment to ambient conditions	
Test	Test function for displaying identcode and for checking weighing platform	
Identification data	4 memories for 20 alphanumeric characters, can be recalled with keys A to D	
	Each memory can be assigned a fixed name which can be written in the marking field next to the corresponding key	
	25 memories for frequently used identification data	
Info function	Displays of current weighing data, identification data and memories at the press of a button	
Date and time	For printout or output via the data interface	
	 Quartz-controlled, 12 or 24-hour display, automatic calendar function, Europe or US format, protected against power failures 	


Technical data and accessories ID7-Base


Interface RS232-ID7			
Interface type	Voltage interface as per EIA RS232C/DIN 66020 (CCITT V.24/V.28)		
Control signals	• Signal level 0 (for $R_L > 3 \text{ k}\Omega$): $-3 \text{ V}25 \text{ V}$ (low level)		
DTR, DSR	• Signal level 1 (for $R_L > 3 \text{ k}\Omega$): +3 V - +25 V (high level)		
Data lines	• Signal level 0 (for R _L > 3 k Ω): +3 V - +25 V (high level)		
TXD, RXD	• Signal level 1 (for R _L > 3 k Ω): -3 V -25 V (low level)		
Interface parameters	Operating mode full duplex Transmission type bit serial, asynchronous Transmission code ASCII Data bits 7/8 Stop bits 1/2 Parity parity even, parity odd, parity space, parity mark, no parity Baud rate 150, 300, 600, 1200, 2400, 4800, 9600, 19200 baud		
Socket 70 06 8 01 50 04 20 External view	8-pin circular connector, socket Pin 1 Ground Pin 2 TXD, transmission line of scale Pin 3 RXD, receiving line of scale Pin 4 DTR, Data Terminal Ready Pin 5 +5 V, max. 250 mA (factory setting, for COM1 – COM6) or +12 V, max.100 mA (for COM2 – COM6 only); configuring of Pin 5, see section 9.6 Pin 6 Signal Ground Pin 8 DSR, Data Set Ready		
Cable	 Shielded, stranded in pairs, max. 15 m Cable resistance ≤ 125 Ω/km Cable cross section ≥ 0.14 mm² Cable capacity ≤ 130 nF/km 		

Dimensions









Dimensions in mm

Technical data and accessories ID7-Base

8.2 Accessories

Applications	Order No.	
ControlPac-ID7	Basic functions, checking, classifying	22 001 081
CountPac-ID7	Basic functions, convenient counting, totalizing	22 001 075
DataPac-ID7	Basic functions, data communication	22 001 077
DosPac-ID7	Basic functions, dispensing, filling	22 001 079
DosPac-R-ID7	Basic functions, multi-component dispensing	22 001 080
FormPac-ID7	Basic functions, formulation, dispensing	22 001 076
SumPac-ID7	Basic functions, totalizing, inventory management	22 001 078

Weighing platform con	Order No.	
IDNet ID7	Connection for an IDNet weighing platform	22 001 082
	Max. of 2 additional connections possible	
Analog Scale ID7	Connection for a weighing platform with an analog signal output	22 001 083
	 Max. of 1 analog weighing platform connection possible 	
LC IDNet R/G	Connection set for connecting METTLER TOLEDO R/G scales to IDNet connection of ID7-Base	00 229 110
LC IDNet B	Connection set for connecting METTLER TOLEDO B scales to IDNet connection of ID7-Base	00 229 225
GD17	Connection set for connecting DigiTOL scales to IDNet connection of ID7-Base	00 507 073

Serial data interfaces		Order No.
CL20mA-ID7	CL 20 mA interface	22 001 084
Accessories for CL20mA-ID7	CL cable, 3 m Mating connector, 7-pin Second-display cable CL20mA-ID7 – ID1 Plus/ID3s/ID7, 10 m Extension cable for second display, 10-pin, 10 m Adapter cable PE / CL, 0.3 m	00 503 749 00 503 745 00 504 511 00 504 134 22 003 029
RS232-ID7	RS232 interface	22 001 085
Accessories for RS232-ID7	RS232 cable/DTE, 3 m RS232 cable/DCE, 3 m RS232 cable/PC, 3 m RS232 cable/9-pin, 3 m Mating connector, 8-pin	00 503 754 00 503 755 00 504 374 00 504 376 00 503 756
RS422-ID7	RS422 interface, electrically isolated	22 003 031
RS485-ID7	RS485 interface, electrically isolated	22 001 086
Accessories for RS422-ID7/RS485-ID7	RS422/485 cable, 6-pin, open end, 3 m Mating connector, 6-pin	00 204 933 00 204 866
8-ID7 relay box	8 digital inputs, 8 digital outputs, for connection to RS485-ID7	22 001 089
Accessories for 8-ID7 relay box	RS422/485 cable, 6-pin, open end, 3 m Power supply unit for 8-ID7 relay box, 24 V DC	00 204 933 00 505 544

Digital inputs/outputs		Order No.
4 I/O-ID7	4 digital inputs, 4 digital outputs	22 001 087
4-ID7 relay box	Relay box for 4 I/O-ID7; 4 digital inputs, 4 digital outputs, for connection to 4 I/O-ID7	22 001 088
Accessories for 4-ID7 relay box	Cable for 4 I/O-ID7, 19-pin, open end, 10 m Mating connector, 19-pin	00 504 458 00 504 461
8-ID7 relay box	8 digital inputs, 8 digital outputs, for connection to RS485-ID7	22 001 089
Accessories for 8-ID7 relay box	RS422/485 cable, 6-pin, open end, 3 m Power supply unit for 8-ID7 relay box, 24 V DC	00 204 933 00 505 544

Technical data and accessories ID7-Base

Digital/analog interface		Order No.
Analog Output-ID7	Digital/analog output 0 - 10 V, 0 - 20 mA or 4 - 20 mA	22 001 090
Accessories for Analog Output-ID7	Cable for Analog Output-ID7, 5-pin, 3 m Mating connector, 5-pin	00 204 930 00 205 538

Alibi memory		Order No.
Alibi Memory-ID7	Archiving of certification-relevant weighing data	22 001 663

Printer		Order No.
GA46	Printer in separate tabletop housing of nickel chromium steel, protection type IP21 Printing of weighing data and barcodes on 62 mm wide thermal paper Interface RS232, cable approx. 2.5 m For technical details see data sheet GA46	00 505 471
GA46/0.4 m	As for GA46, however with 0.4 m cable	00 507 229
GA46-W	As for GA46, however with integrated paper winding device and transparent PVC cover, protection type IP65	00 505 799
GA46-W/0.4 m	As for GA46-W, however with 0.4 m cable	00 507 230
Accessories for GA46	Protective cover for GA46	00 507 224

External keypad		Order No.
AK-MFII	Compact, alphanumeric membrane keypad for connection to the standard-equipment 5-pin MFII circular connector Housing of all nickel chromium steel, protection type IP65 Dimensions (W x D x H): 380 mm x 158 mm x 30 mm Cable approx. 1 m	00 505 490
Accessories for AK-MFII	Keypad-terminal adapter	00 208 047

Other accessories		Order No.
Protective covers	3 pieces	22 001 091
Wall bracket	black, plastic-coated completely rust-proof	00 504 129 00 504 130
Floor stand	black, plastic-coated completely rust-proof	00 504 131 00 504 132
Stand socket	black, plastic-coated completely rust-proof	00 503 700 00 503 701
Bracket stand	black, plastic-coated completely rust-proof	00 504 127 00 504 128

Appendix ID7-Base

9 Appendix

9.1 Fix-tare

→ Copy this list and enter your tare constants.

Fix-tare no.	Appl. block no.	Tare value	Comment
1	21		
2	22		
3	23		
4	24		
5	25		
6	26		
7	27		
8	28		
9	29		
10	30		
11	31		
12	32		
13	33		
14	34		
15	35		
16	36		
17	37		
18	38		
19	39		
20	40		
21	41		
22	42		
23	43		
24	44		
25	45		

9.2 Delta-fix

→ Copy this list and enter your DeltaTrac constants.

Delta-fix no.	Appl. block no.	Target value	Tolerance	Comment
1	46			
2	47			
3	48			
4	49			
5	50			
6	51			
7	52			
8	53			
9	54			
10	55			
11	56			
12	57			
13	58			
14	59			
15	60			
16	61			
17	62			
18	63			
19	64			
20	65			
21	66			
22	67			
23	68			
24	69			
25	70			

9.3 Fixed texts

→ Copy this list and enter your fixed texts.

Fixed text no.	Appl. block no.	Content	Comment
1	71		
2	72		
3	73		
4	74		
5	75		
6	76		
7	77		
8	78		
9	79		
10	80		
11	81		
12	82		
13	83		
14	84		
15	85		
16	86		
17	87		
18	88		
19	89		
20	90		appears after switch-on

Code	Appl. block no.	Name	Content
Code A	94		
Code B	95		
Code C	96		
Code D	97		

ID7-Base Appendix

9.4 Table of representable characters

hex	deci	ASCII US	hex	deci	ASCII US	hex	deci	ASCII US	hex	deci	ASCII US	hex	deci	ASCII US
00	0	NUL	34	52	4	68	104	h	9C	156	£	D0	208	Ш
01	1	SOH	35	53	5	69	105	i	9D	157	¥	D1	209	₹
02	2	STX	36	54	6	6A	106	j	9E	158	Rs	D2	210	Ĺ
03	3	ETX	37	55	7	6B	107	k	9F	159	f	D3	211	L
04	4	EOT	38	56	8	6C	108	I	AO	160	á	D4	212	F
05	5	ENQ	39	57	9	6D	109	m	A1	161	ĺ	D5	213	F
06	6	ACK	ЗА	58	:	6E	110	n	A2	162	Ó	D6	214	Г
07	7	BEL	3B	59	;	6F	111	0	A3	163	Ú	D7	215	
80	8	BS	3C	60	<	70	112	р	A4	164	ñ	D8	216	"
09	9	HT	3D	61	=	71	113	q	A5	165	Ñ	D9	217	j
OA	10	LF	3E	62	>	72	114	r	A6	166	a	DA	218	Г
OB	11	VT	3F	63	?	73	115	S	A7	167	0	DB	219	Ė
OC	12	FF	40	64	@	74	116	t	A8	168	Ś	DC	220	
0D	13	CR	41	65	Α	75	117	u	A9	169	<u></u>	DD	221	Ī
OE	14	SO	42	66	В	76	118	V	AA	170	\neg	DE	222	ī
OF	15	SI	43	67	С	77	119	W	AB	171	1/2	DF	223	i
10	16	DLE	44	68	D	78	120	Χ	AC	172	1/4	EO	224	α
11	17	DC1	45	69	Е	79	121	У	AD	173	i	E1	225	ß
12	18	DC2	46	70	F	7A	122	Z	AE	174	«	E2	226	Γ
13	19	DC3	47	71	G	7B	123	{	AF	175	»	E3	227	Т
14	20	DC4	48	72	Н	7C	124	Ì	B0	176	**	E4	228	Σ
15	21	NAK	49	73	1	7D	125	}	В1	177		E5	229	σ
16	22	SYN	4A	74	J	7E	126	~	B2	178		E6	230	μ
17	23	ETB	4B	75	K	7F	127	\triangle	В3	179	Ī	E7	231	τ
18	24	CAN	4C	76	L	80	128	reserved	В4	180	4	E8	232	Φ
19	25	EM	4D	77	М	81	129	ü	B5	181	╡	E9	233	Θ
1A	26	SUB	4E	78	N	82	130	é	В6	182	-ji	EA	234	Ω
1B	27	ESC	4F	79	0	83	131	â	В7	183	 Ti	EB	235	δ
1C	28	FS	50	80	Р	84	132	ä	B8	184	 7	EC	236	00
1D	29	GS	51	81	Q	85	133	à	В9	185	4	ED	237	Ø
1E	30	RS	52	82	R	86	134	å	BA	186	Ï	EE	238	3
1F	31	US	53	83	S	87	135	Ç	BB	187	 1	EF	239	Π
20	32	SP	54	84	T	88	136	ê	BC	188	<u>اَ</u>	FO	240	≡
21	33	!	55	85	U	89	137	ë	BD	189	Ш	F1	241	±
22	34	II	56	86	V	88	138	è	BE	190	╛	F2	242	\geq
23	35	#	57	87	W	8B	139	Ï	BF	191	٦	F3	243	\leq
24	36	\$	58	88	Χ	8C	140	î	CO	192	Ĺ	F4	244	ſ
25	37	%	59	89	Υ	8D	141	ì	C1	193	Τ.	F5	245	j
26	38	&	5A	90	Z	8E	142	Ä	C2	194	Т	F6	246	÷
27	39	,	5B	91	[8F	143	Å	C3	195	ŀ	F7	247	≈
28	40	(5C	92	\	90	144	É	C4	196	<u>-</u>	F8	248	0
29	41)	5D	93]	91	145	œ	C5	197	+	F9	249	•
2A	42	*	5E	94	٨	92	146	Æ	C6	198	F	FA	250	•
2B	43	+	5F	95	_	93	147	ô	C7	199	⊩	FB	251	$\sqrt{}$
2C	44	,	60	96	-	94	148	Ö	C8	200	Ë	FC	252	n
2D	45	-	61	97	а	95	149	Ò	C9	201	F	FD	253	2
2E	46		62	98	b	96	150	û	CA	202	<u> </u>	FE	254	
2F	47	/	63	99	С	97	151	ù	CB	203	ī	FF	255	
30	48	0	64	100	d	98	152	ÿ	CC	204	Ë			
31	49	1	65	101	е	99	153	Ö	CD	205	=			
32	50	2	66	102	f	9A	154	Ü	CE	206	<u> </u>			
33	51	3	67	103	g	9B	155	¢	CF	207	⊥			

Appendix ID7-Base

9.5 Opening/closing ID7-Base weighing terminal



CAUTION

- → The ID7-Base weighing terminal may only be opened by authorized personnel!
- → Always pull the mains plug before opening the unit.

Opening

- 1. Remove screws on underside of cover.
- 2. Lay down cover toward front.

Closing

- 1. Lay device on cover and fix slightly in place with 3 screws.
- 2. Press unit into cover so that 3 engaging springs engage.
- 3. Tighten screws.



CAUTION

The IP68 protection type is only ensured when the weighing terminal is properly closed again.

- → The 3 engaging springs must be completely engaged.
- → Make sure that keypad cable is not pinched.


9.6 Configuring Pin 5 on RS232-ID7 interface

Pin 5 of the RS232-ID7 interface can be configured for the connection of devices which require a 12 V supply voltage (with COM2 - COM6 only).

- 1. Open weighing terminal.
- 2. Change position of jumper W1 on RS232-ID7 board.

Jumper W1	Voltage at Pin 5
Pin 1 and 2 (factory setting)	5 V
Pin 2 and 3	12 V

3. Close weighing terminal again.



ID7-Base Index

10 Index

Display update 30 Weighing process Dynamic weighing 14, 27, adapter 29,65 Accessories 68 Read-only memory 18 What to do if ...? 61 Acoustic signal 49 65 Recall information 18 Additional functions 11 Representable characters 75 Ε Additive tare function 15 Reset scale 29 Edit data string 36, 37 Alibi Memory ID7 5 Reset terminal 25 Error messages 51 Alibi Memory-ID7 31 Response format 40 External keyboard 26 **Alphanumeric** Restart 30 External keypad 20, 70 identification 17 RS... 31 Alphanumeric keypad 20, 70 Alphanumeric printout 48 Filling 12 Safety precautions 3 Application blocks 37, 48, Function keys 4, 11 Sandwich tare 16 54 Applications 3 Second display 21, 69 ASCII characters 41, 75 Second unit 30 GA46 31 Automatic continuous Serial interfaces 40 Gross 15, 65 Set zero 8, 43, 65 transmission 33 Stability detector 29 Autotara 9, 30 Status byte 52, 53 Autozero 30 Housing 64 String framing 34, 41 Switch keypad on/off 43 Barcode 19, 31, 38, 49 Switch off 8 ID code 7, 16 Basic functions 8 Switch on 8 Identifications 16, 49, 65 Big Weight Display 27 Switch over weighing Interface 4 I/O-ID7 31 Bus Slave 32, 41 platform 10 Interface CL-ID7 31 Interface connections 5, 31, T 64 Certified weighing Tare 9, 44, 65 Interface description 40 platforms 6 Tare read-only memory 9, Interface RS232-ID7 66 Change over weight unit 43 25, 72 Interface type 31 Technical data 64 Check mode 27 Introduction 3 Checkweighing 12 Terminal 64 Classifying 12 Test 65 Cleaning 7 Test weighing platform 16 Keypad 4, 64 Command format 40 Text for A B C D 26 Command overview 42 Text read-only memory 17, Commissioning 6 25, 74 Language 26 Communication 32 Time 27, 65 Configuration print-outs 35 Transfer data 19 М Connect weighing Transfer string 33 Mastermode 22 platforms 6 Transmit buffer 59 METTLER TOLEDO continuous Connections 5 Transmit data record 47 mode 34 Transmit weight value 45 MMR command set 33, 40 D Multiplicative tare function 15 Data formats 41 Date 27, 65 Unit changeover 65 DeltaTrac 11, 26, 45, 65 Operating mode 32 DeltaTrac read-only Vibration adapter 29, 65 memory 26, 73 DeltaTrac target values 13, Personal code 27 45 Power supply 6 Weighing 10 Dialog mode 33, 40 Print 19 Weighing functions 65 Digital inputs/outputs 60, 69 Print mode 33, 35

Weighing platform

connections 64, 68

Printout 48

Display 4, 48, 64

Display Mode 63

Mettle	er-Toledo (Albstadt) GmbH	D-72458 Albstadt	T ++49-7431-14 0	F -14 232
AT AU	Mettler-Toledo Ges.m.b.H. Mettler-Toledo Ltd.	1100 Wien Victoria 3207	T ++43-1-604 19 80 T ++61-3-9646 45 51	F -604 28 80 F -9645 39 35
BE	N.V. Mettler-Toledo S.A.	1651 Lot	T ++32-2-334 02 11	F -378 16 65
CH	Mettler-Toledo (Schweiz) AG	8606 Greifensee	T ++41-1-944 45 45	F -944 45 10
CN	Mettler-Toledo (Schweiz) Ad Mettler-Toledo (Shanghai) Ltd.	Shanghai 200233	T ++86-21-6485 0435	F -6485 3351
CZ	Mettler-Toledo (Shanghar) Ela. Mettler-Toledo spol, s.r.o.	120 00 Praha 2	T ++42-2-252 755	F -242 475 83
DE	Mettler-Toledo Spot, S.I.o.	35353 Giessen	T ++49-641-50 70	F -507 129
DK	Mettler-Toledo A/S	2600 Glostrup	T ++45-43 27 08 00	F -43 27 08 28
ES	Mettler-Toledo S.A.E.	08038 Barcelona	T ++34-93 223 22 22	F -223 02 71
FR	Mettler-Toledo s.g.	78220 Viroflay-Cedex	T ++33-1-30 97 17 17	F -30 97 16 00
HK	Mettler-Toledo (HK) Ltd.	Kowloon, Hongkong	T ++852-2744 1221	F -2744 6878
HR	Mettler-Toledo d.o.o.	100 10 Zagreb	T ++385-1-233 6317	F -233 6317
HU	Mettler-Toledo Keresked, KFT	1173 Budapest	T ++36-1-257 98 89	F -256 21 75
IN	Mettler-Toledo India Pvt. Ltd.	Mumbai 400 072	T ++91-22-857 0808	F -857 5071
IT	Mettler-Toledo S.p.A.	20026 Novate Milanese	T ++39-02-33 33 21	F -356 2973
JP	Mettler-Toledo K.K.	Osaka 540	T ++81-6-6949 5917	F -6949 5944
KR	Mettler-Toledo (Korea)	Seoul 135-080	T ++82-2-518 2004	F -518 0813
MY	Mettler-Toledo (M)	47301 Petaling Jaya	T ++60-3-703 2773	F -703 8773
NO	Mettler-Toledo A/S	1008 Oslo 10	T ++47-22-30 44 90	F -32 70 02
NL	Mettler-Toledo B.V.	4000 HA Tiel	T ++31-344-63 83 63	F -63 83 90
PL	Mettler-Toledo Sp.z.o.o.	02-924 Warszawa	T ++48-22-651 92 32	F -651 71 72
RU	Mettler-Toledo AO	101000 Moscow	T ++7-095-921 92 11	F -921 63 53
SE	Mettler-Toledo AB	120 08 Stockholm	T ++46-8-702 50 00	F -642 45 62
SG	Mettler-Toledo (S) Pte. Ltd.	Singapore 139944	T ++65-778 67 79	F -778 66 39
SK	Mettler-Toledo spol, s.r.o.	831 03 Bratislava	T ++421-7-5252 170	F -5252 173
SL	Mettler-Toledo d.o.o.	1236 Trzin	T ++61-162-1801	F -161-1789
TH	Mettler-Toledo (Thailand)	Bangkok 10310	T ++66-2-719 64 80	F -719 64 79
TW	Mettler-Toledo (Taiwan)	Taipei	T ++886-2-579 5955	F -579 5977
UK	Mettler-Toledo Ltd.	Leicester, LE4 1AW	T ++44-116-235 70 70	F -236 63 99
US	Mettler-Toledo Inc.	Columbus, Ohio 43085	T ++1-614-438 4511	F -438 4755
Other	countries: Mettler-Toledo AG	8606 Greifensee	T ++41-1-944 22 11	F -944 31 70