

TEST MODE

The Test Mode is entered by shorting two contacts (adjacent to the front of the A600) together momentarily on the underside of the main PCB (Fig. 3). (A screwdriver blade is a suitable tool for this work).


Access is gained through a sealable hole in the base molding - see the below diagram for details. If the scale has been previously sealed, this seal can only be removed by dismantling the scale.

Access to calibration and configuration modes can now be obtained.

The scale will also display sub-division information of weight in the unit price display.

To exit the Test Mode either repeat the entry procedure or unplug the scale from the line supply.

Fig. 3 Underside of Base



CONFIGURATION**CONFIGURATION PROCEDURE**

Refer to Figure 4 - Display & Keyboard Arrangements - for list of function keys.

The scale can be configured from a variety of options detailed in the Option Table, page .

To enter an option, put the scale into Test Mode (Section 5) and then follow the step by step instructions detailed below:

<u>ACTION</u>	<u>DISPLAY</u>
Short out 2 contacts	WD (nn.nn) UPD (nn) TPD (tEst)
Press ZERO (select configuration mode "C1")	WD (BLANK) UPD (BLANK) TPD (C1)
Press SAVE (Enter configuration mode)	WD (BLANK) UPD (XXXXXX) TPD (XXXXXX)
Enter DIGIT CONFIGURATION CODE (Using numeric keys and function keys as indicated in Fig. 4)	WD (BLANK) UPD (01D2A) TPD (00300)
Press SAVE (Store new configuration)	WD (nn.nn) UPD (nn) TPD (tEst)

This completes the configuration procedure.

Note: X = Undefined value
nn.nn = Applied Load
nn = Internal counts

OPTION TABLES

The 10 digit code used to configure the operation of the scale is formed by adding the numeric equivalent value of each option in each digit together (unless otherwise stated) to form a hexadecimal number. The example given is for a 30lb scale without 1/4 or 1/2 keys.

DIGIT	OPTION FUNCTION	OPTION VALUE	SUM OF OPTIONS	HEXADECIMAL VALUE
1	TP ROUNDING NEAREST 1 TP ROUNDING NEAREST 5 TP ROUNDING NEAREST 10 10 % ZERO RANGE LOWER PRICE BASE	0 1 2 4 8	= 0	0
2	NO FUNCTION LISTED BELOW BLEEP INHIBIT BEHIND ZERO RETAINED UNIT PRICE INHIBIT KEYBOARD TIME OUT DUMMY ZERO UNIT PRICE	0 1 2 4 8	= 1	1
3	SEMI SELF CANCELING TARE -VE TARE DISPLAY RETAINED TARE KEYBOARD ENTER TARE TARE INTERLOCK	0 1 2 4 8	1+4+8 = 13	D
4	15 LB X 1/8 OZ. 15 KG X 10 G 15 LB X 0.01 LB 30 LB X 0.01 LB 7.5 KG X 5 G 15 KG X 5 G 25 LB X 1/4 OZ	0 1 2 3 4 5 6	= 3	3
5	NO DECIMAL POINT/COMMAS 1 DECIMAL PLACE 2 DECIMAL PLACE 3 DECIMAL PLACE TAIL ON DECIMAL POINTS US KEYBOARD	0 1 2 3 4 8	2+8 = 10	A
6	GENERAL EXPORT UK VARIANTS WEIGHT FREEZE CANADIAN INTERLOCK	0 1 2 4	= 0	0
7	NO FUNCTION LISTED BELOW DISABLE STANDBY KEY DISABLE + KEY DISABLE SAVE KEY DISABLE ZERO KEY	0 1 2 4 8	= 0	0
8	NO FUNCTION LISTED BELOW DISABLE 1/4 KEY DISABLE 1/2 KEY DISABLE TARE KEY DISABLE CLEAR KEY	0 1 2 4 8	1+2 = 3	0
9	NO FUNCTION LISTED BELOW SALAD BAR TARE	0 1	= 0	0
10	NO FUNCTION	0	= 0	0

HEX CONVERSION TABLE

DECIMAL	0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
HEX VAL	0	1	2	3	4	5	6	7	8	9	A	B	C	D	E	F

EXAMPLE

The below example details the standard 301b U.S. configuration. If other options are required see the Option Table on the previous pages.

DIGIT 1 = 0
DIGIT 2 = 1
DIGIT 3 = 1 + 4 + 8 = 13 = D
DIGIT 4 = 3
DIGIT 5 = 2 + 8 + = 10 = A
DIGIT 6 = 0
DIGIT 7 = 0
DIGIT 8 = 3
DIGIT 9 = 0
DIGIT 10 = 0

Thus the eight digit code = (MSD) 01D3A00300 (LSD) is entered MSD first.

CALIBRATION

Before calibrating the load cell, ensure that the configurable options have been set. The following details the calibration procedure:

<u>ACTION</u>	<u>DISPLAY</u>
A Short out 2 contacts	WD (nn.nn) UPD (nn) TPD (tEst)
B Press ZERO (Select configuration mode)	WD (blank) UPD (C1) TPD (blank)
C Press ZERO (Select calibration mode)	WD (blank) UPD (C2) TPD (blank)
D Press SAVE <i>(Pnk-Prck)</i> (Select calibration mode)	WD (xx.xx) UPD (nn) TPD (2ErO)
E Empty weigh plate and press SAVE <i>(Pnk-Prck)</i>	WD (xx.xx) UPD (nn) TPD (FULL)
F Apply full load to weigh plate and press SAVE <i>(Pnk-Prck)</i>	WD (xx.xx) UPD (nn) TPD (FinE)
G Remove full load and press $1/4$ to zero the scale <i>(1g/Lb)</i>	WD (00.00) UPD (03/04) TPD (FinE)
H Apply full load and fine adjust the display reading using the STANDBY <i>(THIS)</i> key to increase and the + key to reduce the reading <i>Accu.</i>	WD (30.01) UPD (03/04) TPD (FinE)
I Repeat steps G and H until no further adjustment is required	WD (30.00) UPD (03/04) TDP (FinE)
J Press SAVE <i>(1g/Lb)</i> at 30lb when ZERO and FULL LOAD readings are correct	WD (30.00) UPD (03/04) TPD (2ErO)
K Remove FULL LOAD from weigh plate and press SAVE <i>(Pnk-Prck)</i>	WD (00.60) UPD (03/04) TPD (bALAnC)
L Press $1/4$ key <i>(1g/Lb)</i>	WD (00.00) UPD (03/04) TPD (tEst)

This completes the calibration of the A600, to return to normal mode turn the scale off and on or short out the two contacts as before.

CALIBRATION (cont.)

- Note 1:** xx.xx = undefined value.
 nn.nn = Applied Weight
 nn = Internal Subdivisions
- Note 2:** In steps G, H and L, the unit price display will show
 07/08 if the 15lb x 0.01 capacities have been selected.
- Note 3:** The changes in no-load and full load output of the load
 cell, due to manufacturing tolerance, are compensated for
 in the microcomputer. Therefore, no adjustments to the
 main board are necessary.