

Avery Weigh-Tronix

THE evolution™ SERIES



## Model E1010 Indicator User's Manual

### **UNITED STATES**

This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

### **CANADA**

This digital apparatus does not exceed the Class A limits for radio noise emissions from digital apparatus set out in the Radio Interference Regulations of the Canadian Department of Communications.

Le présent appareil numérique n'émet pas de bruits radioélectriques dépassant les limites applicables aux appareils numériques de la Class A prescrites dans le Règlement sur le brouillage radioélectrique que edicté par le ministère de2s Communications du Canada.

### **EUROPEAN COUNTRIES**

#### **WARNING**

**This is a Class A product. In a domestic environment this product may cause radio interference in which the user may be required to take adequate measures.**



#### **CAUTION**

**CAUTION: DANGER OF EXPLOSION IF BATTERY IS INCORRECTLY REPLACED.  
REPLACE ONLY WITH THE SAME OR EQUIVALENT TYPE RECOMMENDED BY THE MANUFACTURER.  
DISPOSE OF USED BATTERIES ACCORDING TO THE MANUFACTURER'S INSTRUCTIONS**

**ATTENTION: IL Y A DANGER D'EXPLOSION S'IL Y A REMPLACEMENT INCORRECT DE LA BATTERIE,  
REPLACER UNIQUEMENT AVEC UNE BATTERIE DU MÊME TYPE OU D'UN TYPE ÉQUIVALENT  
RECOMMANDÉ PAR LE CONSTRUCTEUR. METTRE AU REBUT LES BATTERIES USAGÉES  
CONFORMÉMENT AUX INSTRUCTIONS DU FABRICANT".**

**CAUTION: THE POWER SUPPLY CORD IS USED AS THE MAIN DISCONNECT DEVICE, ENSURE THAT THE SOCKET-OUTLET IS LOCATED/INSTALLED NEAR THE EQUIPMENT AND IS EASILY ACCESSIBLE.**

**ATTENTION: LE CORDON D'ALIMENTATION EST UTILISÉ COMME INTERRUPTEUR GÉNÉRAL. LA PRISE DE COURANT DOIT ÊTRE SITUÉE OU INSTALLÉE À PROXIMITÉ DE L'ÉQUIPEMENT ET ÊTRE FACILE D'ACCÈS".**

**Avery Weigh-Tronix reserves the right to change  
specifications at any time.**

# Table of Contents

Table of Contents .....	3
Specifications .....	4
Introduction .....	5
About This Manual .....	5
Setup .....	5
Front Panel .....	6
Keys .....	6
Battery Information .....	8
PLU (Product Look Up) Memory Channels .....	8
Menu Mode .....	9
Indicator Operations .....	10
Gross Weighing .....	10
Tare/Net Weighing .....	10
Accumulator Weighing .....	11
Using Cutoffs .....	11
Checkweighing .....	12
Limit Mode: Entering Upper and Lower Limits .....	13
Sample Mode: Using Product to Set Target Weight .....	13
Performing a Checkweighing Weighment .....	13
Using Cutoffs .....	13
Counting .....	14
Using Cutoffs .....	14
Batch Weighing .....	15
Peak Weighing .....	16
Using Cutoffs .....	16
Communications and Printing .....	17
Error Messages .....	17
Indicator Diagnostics .....	18
Indicator Test Functions .....	18

## IMPORTANT

*This equipment must be routinely checked  
for proper operation and calibration.*

*Application and usage will determine the frequency  
of calibration required for safe operation.*

# Specifications

## Power requirements

- 100-240 Volts AC @ 600 mA
- 50/60 Hz
- Internal battery: 23 hours of continuous operation with one weight sensor; 15 hours of continuous operation with four weight sensors
- Standby mode extends battery life

## Excitation

- 5 volts
- Supports up to four 350-ohm weight sensors

## Analog signal input range

- +/- 12 mV/V

## Analog input sensitivity

- 0.2  $\mu$ V/divisions minimum
- 1.0  $\mu$ V/divisions recommended

## Calibration

- 2 to 5 points stored

## Operational keys

- Tare, Select, Zero, Print, Units, F1, Clear, Mode, Escape, Enter, On/Off, 0-9 numeric and decimal point

## Operational annunciators

- Center of Zero, Motion, Gross, Tare, Net, Battery status
- Under/Target/Over
- Units of measure (LB, KG)
- Peak, Print, OP1, OP2, OP3

## Display

- Seven-digit, seven-segment, 0.8-inch high
- Lighted STN Transmissive
- Display rate Selectable (1, 2, 5, 10)

## Analog to digital conversion rate

- 60 times per second

## Unit of measure:

- Three, independently programmable
- Pounds, Kilograms, Custom

## Capacity selections

- 999,999 with decimal located from zero to five places

## Incremental selections

- Multiples and sub-multiples of 1, 2, 5

## Programmable selections

- Zero range, motion detection, automatic zero tracking, five-point linearization

## Time and date / RAM

- Battery backed up real time clock and RAM

## Internal resolution

- 41,248,140 counts per mV/V per sec

## Standard inputs

- Three logic level inputs for: Zero, Print, Tare, Units, F1

## Standard outputs

- Three cutoff outputs, open collector design
- Serial port RS-232 or 20mA current loop, or RS-422 or RS-485

## Serial Command Inputs

- Programmable serial response to ASCII character input, SMA protocol

## Self diagnostics

Display, keys, inputs, outputs, serial port,

## Circuitry protection

- RFI, EMI, and ESD protection

## Options

- Trips Interface Unit (TIU3)

## Operating applications

- General weighing, Simple counting, Check weighing,
- Peak measurement, Batching, Remote display

## Operating temperature

- 14 to 104° F (-10 to 40° C) approved
- -4 to 140° F (-20 to 60° C) non-legal
- 10 to 90% noncondensing humidity

## Enclosure

- Stainless steel NEMA 6/4X

## Dimensions:

- 9.25" W x 9.25" H x 4.5 " D  
(23.5cm W x 23.5cm H x 11.4cm D)  
(without mounting bracket)
- 9.75" W x 11" H x 7" D  
(24.8cm W x 28cm H x 17.8cm D)  
(with mounting bracket)

## Weight: 11 lb, 5 kg

## Agencies:

- NTEP CC# 04-029  
Class III/IIL:10,000 divisions
- OIML Cert. No. R76/1992-GB1-04.09  
Class III: 10,000 divisions
- Canadian Weights and Measures pending
- UL/CUL
- CE marked

# Introduction

The Model E1010 is an easy to use, uncomplicated indicator for general weighing applications. It is ideal for bench scales, floor scales and tank weighing applications. The display includes a multi-segment fan graph for fast visual awareness for checkweighing. The indicator can perform counting functions, peak weight functions, act as a remote display and operate on battery power. The indicator also has 10 PLU (Product Look Up) memory channels for storing data.

Communication port allows connection to a printer, remote display or computer. The indicator also has three setpoint controls and can accommodate a footswitch for zero, print or tare function.

All this in a NEMA 6/4X rated enclosure.

## About This Manual

Major sections of this manual are headed by titles in a black bar like *Introduction* above. Subheadings appear in the left column. Instructions and text appear on the right side of the page. Occasionally notes, tips, and special instructions appear in the left column.

# Setup



*The Model E1010 is battery powered.*

**Charge the battery overnight before using the indicator on battery power only.**

*The unit can be run on the transformer if the battery is drained or absent.*


*See Battery Information for more information.*

Your indicator will be installed by a qualified Avery Weigh-Tronix distributor. They will make the required connections to your scale and peripheral devices.

1. With the unit plugged in, see note at left, press and hold the  switch until the display lights up, then release the key.
2. The indicator powers up in normal operation mode.

# Front Panel

The front panel, shown in Figure 1, consists of the keys and display.



**Figure 1**  
E1010 front panel

## Keys

*Never press a key with anything but your finger. Damage to the overlay may result if sharp or rough objects are used.*

The functions of the keys on the front panel are listed below.



Press the **TARE** key to perform a tare function. Also acts as a left arrow key when in the User menu.



Press the **SELECT** key to toggle between Gross, Tare, Net, Count, Gross Accumulator, Net Accumulator, Transaction Counter, Piece Weight, and Peak. This is dependent on the current application. Also acts as an up arrow key when in the User menu.



Press the **ZERO** key to zero the display.



Press the **PRINT** key to send information to a peripheral device through the Comm port. Also acts as a down arrow key when in the User menu.



Press the **UNITS** key to scroll through the available units of measure while in normal operating mode. Also acts as a right arrow key when in the User menu.



Press the **F1** key to select application specific choices. Press and hold to access the cutoffs (trips) function. Also used to access PLU (Product Look Up) memory channels.



Press the **C/CE** key to clear entries.



Press the **MODE** key to scroll through the enabled applications. The application name is briefly displayed when key is released.



Press the **ESC** key to escape a function or return to normal operation mode. Press and hold to access the password display for the User menu.



Press the **ENTER** key to accept displayed choices.



Use the numeric keypad to enter values.

For example:

- ID entry
- Setpoint target entry
- Preset tare entry
- Password entry
- Key in a print format number (#1-9) and press **PRINT** to print a custom format.



To turn the unit on, press and hold the **ON/OFF** key until the display turns on. To turn the unit off, press and hold the **ON/OFF** key until the unit turns off.

## Battery Information

*When the indicator goes to sleep you must press the ON/OFF switch to restart the indicator.*

This unit contains a sealed rechargeable 6 volt, 3.0Ah, lead-acid battery. Life expectancy of this battery is 3-5 years in standby use or:

180 charging cycles (approx.) if discharged 100%  
400 charging cycles (approx.) if discharged 50%  
1200 charging cycles (approx.) if discharged 30%

Battery life is 23 hours with one 350 ohm weight sensor and 15 hours with four 350 ohm weight sensors. Recharge time from complete discharge is 14 hours while powered up and in service (single loadcell). The AC adapter/charger will charge the battery as it powers the indicator.

The charger has a 12 VDC 800 mA output with center positive connection.

## PLU (Product Look Up) Memory Channels

*If there are preset tares in the PLUs, you cannot enter a keyboard or pushbutton tare. Preset tares are enabled and entered under the Supervisor menu. See the Service Manual for instructions.*

*If preset tares are not enabled, any tare you enter by keyboard or pushbutton method will be active for all PLUs.*

This indicator has 10 channels of memory called PLU or Product Look Up. Each channel can contain the following information:

Channel #  
ID#  
Tare  
Gross Accum.  
Net Accum.  
Total  
TARGET OP1  
TARGET OP2  
TARGET OP3  
Lower Limit  
Upper Limit  
Count Accum.  
Piece Weight  
Peak Weight

1. To activate or recall a PLU, key in the desired channel number (1-10) and press the **F1** key...  
The PLU channel is active. Any of the items listed above that have values are activated. Any values that are listed above that change while this PLU is active are stored, ie; accumulator, count, etc.
2. PLU channels can be cleared by using a password protected menu. These instructions are found in the *Service Manual*. You can also print a report of all the PLU channels in the same password protected menu.

## Entering an ID Number

You can enter an ID number which is then part of the active PLU channel. To enter an ID, key in a number on the keypad then press the **ENTER** key.


# Menu Mode

User menu password is 111.  
You must key in the password  
within 10 seconds or the  
display returns to normal  
operation mode.

The E1010 has a User menu which you can use to do the following:

- Audit the number of configurations and calibrations performed
- See software information
- Display test
- Button test
- Serial port test

1. Access the User menu by pressing and holding the **ESC** key for 3-5 seconds.  
**PASS\_** is displayed.
2. Key in the User menu password = 111 and press the **ENTER** key. Figure 2 shows a flowchart of the User menu items. Use the keys shown in the dotted box in Figure 2 to navigate through the menu and choose the items you want.



**Figure 2**  
User menu flowchart



Specific instructions on the User menu appear in the section *Indicator Diagnostics* later in the manual.

# Indicator Operations

*When the indicator goes to sleep you must press the ON/OFF switch to restart the indicator.*

*This indicator has a 10 channel PLU (Product Look Up) memory. To access a memory channel, press a number from 1 to 10, then press the F1 key.*

The E1010 comes equipped with several weighing applications;

- Accumulator weighing (default setting)
- Batch weighing
- Checkweigher
- Counting
- Peak capture
- Remote display

These applications are enabled using a password protected Service menu. See the Service Manual for instructions on enabling applications and clearing accumulators.

The accumulator application comes as the default application. You can do gross weighments, tare/net weighments and accumulator functions. Below are instructions for each.

## Gross Weighing

*To change unit of measure, press the UNITS key.*

To perform gross weighing, power up the unit and follow these steps:

1. Empty the scale and press **ZERO** key to zero the display. . .  
*0* is displayed and gross and center of zero annunciators are lit.
2. Place item to be weighed on the scale. . .  
Weight is displayed.

## Tare/Net Weighing

To perform a net weighment, power up the unit and follow these steps:

1. Empty the scale and press **ZERO** key to zero the display. . .  
*0* is displayed and gross and center of zero annunciators are lit.
2. Place item to be tared on the scale. . .  
Weight is displayed.
3. Press the **TARE** key. . .  
*0* is displayed and net annunciator is lit.
4. Place material to be weighed on the scale. . .  
Net weight of material is displayed and net annunciator is lit.
5. Repeatedly press the **SELECT** key to scroll through gross, tare, and net values. Remove the weight from the scale and press **TARE** to return to gross mode.

## Accumulator Weighing

Press the **MODE** key to scroll through the enabled applications.

You can use tare/net weighing with the accumulator application. The accumulator stores both gross and net totals for later recall.

The accumulator is memory that collects individual weighments (gross and net) and stores the totals. These totals can be recalled at any time and the number of weighments included in the totals can be displayed. With the proper password all information can be deleted. See the *Service Manual*.

The accumulator maximum is 999,999. It does not rollover and start over at 0.

To use the accumulator, power up the unit and follow these steps:

1. Empty the scale and press the **ZERO** key to zero the display. . .  
**0** is displayed and gross and center of zero annunciators are lit.
2. Place item on the scale. . .  
Weight is displayed.
3. You can press the **PRINT** or **F1** key to add weight to the accumulator. If you press **PRINT**, the weight is accumulated and the information printed. If you press **F1**, the weight is accumulated. Scale weight must return to zero before another weighment can be accumulated.
4. Repeat 2 and 3 for each weighment you want to accumulate.
5. To review the accumulator total and the number of weighments, remove all weight from the scale and press the **SELECT** key repeatedly. . .  
1st press = Net weight displayed  
2nd press = Tare weight displayed  
3rd press = Gross total of all weighments is displayed  
4th press = Net total of all weighments is displayed  
5th press = Number of weighments is displayed  
6th press = Display returns to gross weigh mode

You need the supervisor's password to clear the accumulator. See the *Service Manual* for instructions.

## Using Cutoffs

You can use the cutoff (or trips) function if so desired while in the Accumulator application. The output will turn on when weight goes above the target set for that output and will remain on until the weight falls below the target. Follow these steps to set up to three outputs:

1. With the indicator powered up, press and hold the **F1** key until. . .  
**OP1** is displayed.
2. Press the **PRINT** key to set the value for the output. . .  
Key in a value and press the **F1** key to accept the value. **OP1** will be displayed.  
You can scroll through all three outputs by using the **TARE** and **UNITS** keys.
3. Press the **UNITS** key. . .  
**OP2** is displayed.
4. Repeat steps 2 and 3 for each output. Press **ESC** key to return to normal operation with the ingredients active. Indicator will automatically return to normal weighing mode after OP3 value is entered.

## Checkweighing

This indicator has a 10 channel PLU (Product Look Up) memory. To access a memory channel, press a number from 1 to 10, then press the F1 key.

The graph is based off of net weight so if a tare is active only the net weight is considered for checkweighing. If there is no tare, gross weight is used as the basis for the graph.


This section applies if your indicator has the checkweighing application active. Applications are activated through a password protected menu. See the *Service Manual* for instructions.

Checkweighing allows a quick, visual check of the acceptability or unacceptability of an item's weight.

You can set your target weight in one of two ways. The mode is set in a password protected menu. See the *Service Manual* for instructions. The two modes are explained below:

### Limit Mode


Enter the upper and lower limits for your item and the indicator will use those values to run the display. See Figure 3.



**Figure 3**  
Limit mode

### Sample Mode


Place a correct weight "product" on the scale and press the F1 key. The indicator will use this weight to run the display. Upper and lower limits will automatically be 1 division above and below the target weight respectively. Figure 4 shows how the graphic display works in Sample mode. Each graduation is equal to 1 scale division. The TARGET light stays lit if weight is  $\pm 1$  division of the target weight.



**Figure 4**  
Sample mode

Directions for each mode follows.

## Limit Mode: Entering Upper and Lower Limits



Follow these steps to setup and use the checkweigher function if limit mode is enabled, where you set upper and lower weight limits:

1. Press the **F1** key...  
**Up** is displayed followed by an underscore cursor.
2. Key in the upper weight limit. Press the **F1** key...  
**Lo** is displayed.
3. Key in the lower weight limit. Press the **F1** key...  
The indicator returns to normal weigh mode.
4. Place items on the scale and the display will show if the weight is over, under or acceptable based on the limits you have set.

## Sample Mode: Using Product to Set Target Weight


Follow these steps to setup and use the checkweigher function if sample mode is enabled, where you set target weight based on an actual “product”:

1. Place a sample, of the correct weight, on the scale...  
Weight is displayed.
2. Press the **F1** key.  
The target weight is captured, the indicator switches to net mode, the display reads **0** and your indicator is ready to use as a checkweigher. The target weight will be the same as your sample item and the target will stay lit whenever an item's weight is within  $\pm 1$  division of the target weight.

## Performing a Checkweighing Weighment

1. With your target weight set, as described in one of the previous two sections, place your item on the scale...  
If the weight equals the acceptable value, the TARGET annunciator lights. If the weight varies from the target value, upper or lower segments may be lit and the weight will show a plus or minus weight reading for the deviation from the target weight.
2. Repeat step 1 for all products of this weight.

## Using Cutoffs



You can use the cutoff (or trips) function if so desired while in the checkweigher application. Follow these steps to set up to three outputs:

1. With the indicator powered up, press and hold the **F1** key until...  
**OP1** is displayed.
2. Press the **PRINT** key to set the value for the output...  
Key in a value and press the **F1** key to accept the value. **OP1** will be displayed.  
You can scroll through all three outputs by using the **TARE** and **UNITS** keys.
3. Press the **UNITS** key...  
**OP2** is displayed.
4. Repeat steps 2 and 3 for each output. Press **ESC** key to return to normal operation with the ingredients active. Indicator will automatically return to normal weighing mode after OP3 value is entered.

## Counting

*This indicator has a 10 channel PLU (Product Look Up) memory. To access a memory channel, press a number from 1 to 10, then press the **F1** key.*

This section applies if your indicator has the counting application active. Applications are activated through a password protected menu. See the *Service Manual* for instructions.

Follow these steps to perform a counting function with the E1010:

1. In gross weight mode, press the **F1** key...  
**PCS** is displayed followed by an underscore cursor.
2. Enter the sample size you desire (see note at left) and press **ENTER**...  
**Add X** is displayed. X is the sample size you keyed in.
3. Place the correct number of parts on the scale and press the **ENTER** key. **BUSY** is briefly displayed, followed by one of two possible displays:
  - a. If the sample met the minimum sample requirements, the display will show the correct number of parts on the scale.
  - b. If the sample size was not large enough, the display will tell you how many more parts to add to the scale (For example: **5** might be displayed.) Add the number requested, wait for the scale to stabilize, then press **ENTER** again. The display will read the correct number of parts on the scale.
4. Place the parts on the scale to be counted.

## Using Cutoffs

You can use the cutoff (or trips) function if so desired while in the counting application. Follow these steps to set up to three outputs:

1. With the indicator powered up, press and hold the **F1** key until...  
**OP1** is displayed.
2. Press the **PRINT** key to set the value for the output...  
Key in a value and press the **F1** key to accept the value. **OP1** will be displayed.  
You can scroll through all three outputs by using the **TARE** and **UNITS** keys.
3. Press the **UNITS** key...  
**OP2** is displayed.
4. Repeat steps 2 and 3 for each output. Press **ESC** key to return to normal operation with the ingredients active. Indicator will automatically return to normal weighing mode after OP3 value is entered.

## Batch Weighing

This indicator has a 10 channel PLU (Product Look Up) memory. To access a memory channel, press a number from 1 to 10, then press the **F1** key.


This section applies if your indicator has the batching application active. The batching application allows you to set three cutoffs or trips based on three progressively larger weights. There are two possible modes of batching; Auto or Manual. Each are explained below.

### AUTO

As weight is added to the scale and the first cutoff point is reached, OP1 annunciator lights and Output #1 is activated. When weight reaches the second cutoff, OP2 annunciator lights and Output #2 activates. When weight reaches the third cutoff, OP3 annunciator lights and Output #3 activates.

### MANUAL

In manual mode, after you begin the batching process, you must press the **F1** key to activate each subsequent output after each output weight is reached.



**Figure 5**  
Output flowchart

## Configuring Outputs

If the system cannot accept the value you key in, **ABORT** will be displayed and display will return to the menu.

Follow these steps and the flowchart in Figure 5 to setup a recipe with three ingredients:

1. With the indicator powered up, press and hold the **F1** key until. . .  
**OP1** is displayed.
2. Key in a value for the first output and press the **ENTER** key to accept the value. . .  
**OP2** is displayed.
3. Repeat step 2 for OP2 and OP3. Once the last output value is entered, the display returns to normal operation with the ingredients active.

## Peak Weighing

*This indicator has a 10 channel PLU (Product Look Up) memory. To access a memory channel, press a number from 1 to 10, then press the **F1** key.*

This section applies if your indicator has the Peak application active.

Peak weight is defined as the highest stable weight reached by the scale. Momentary higher weights that do not stabilize are ignored.

While in Peak mode, the **Peak** annunciator remains lit.

Follow these steps to perform a peak weighment:

1. Empty the scale and press the **ZERO** key to zero the display. . .  
**0** is displayed.
2. Place the item(s) on the scale. . .  
Weight is displayed.
3. After the motion annunciator (~) turns off remove the item(s) from the scale,  
The peak weight is displayed and the center-of-zero annunciator ( $\rightarrow 0 \leftarrow$ ) lights.
4. To clear the peak value, press the **F1** key. . .  
**0** is displayed.
5. Repeat steps 2-4 for other weighments.

Use the **SELECT** key to scroll through G, T, N and peak values

## Using Cutoffs

You can use the cutoff (or trips) function if so desired while in the peak weighing application. Follow these steps to set up to three outputs:

1. With the indicator powered up, press and hold the **F1** key until. . .  
**OP1** is displayed.
2. Press the **PRINT** key to set the value for the output. . .  
Key in a value and press the **F1** key to accept the value. **OP1** will be displayed.  
You can scroll through all three outputs by using the **TARE** and **UNITS** keys.
3. Press the **UNITS** key. . .  
**OP2** is displayed.
4. Repeat steps 2 and 3 for each output. Press **ESC** key to return to normal operation with the ingredients active. Indicator will automatically return to normal weighing mode after OP3 value is entered.

## Communications and Printing

The default serial port parameters are 9600 baud, 8 data bits, no parity and 1 stop bit.

The E1010 provides an RS-232 output for data transmission to a peripheral device. Refer to the Service Manual for RS-232 interface connections.

If your indicator has a peripheral device connected, from the gross/net weighing mode press the **PRINT** key to transmit the selected output(s).

The **PRINT** annunciator will illuminate while data is transmitted and the data configured to be printed will be output to the printer.

### Print Format #1 for weighing applications

G 1234.56 lb<CR><LF>

### Print Format #1 for counting application

Count: 12230

### Print Format #1 for peak application

12230 lb<CR>

## Error Messages


The following are displays you may see if problems occur or if invalid operations are attempted with your indicator:

### Display

### Description



Overrange weight.



Underrange weight.



The unit cannot perform a function. Displayed only while key is held down.




Displayed while a key is pressed when attempting to modify a sealed selection without edit privileges.

# Indicator Diagnostics

## Indicator Test Functions

The user menu lets you test various functions of the indicator. The user menu is shown in Figure 6. Instructions for using the Test portion of the menu are found below.



**Figure 6**  
User Menu

1. Access the User menu by pressing and holding the **ESC** key for 3-5 seconds.  
**PASS\_** is displayed.
2. Key in the User menu password = 111 and press **ENTER**.  
**TEST** is displayed.
3. Press the **PRINT** key.  
**ABOUT** is displayed. Press the **PRINT** key then the **UNITS** key to view the part number and revision level for the software found in your indicator.  
Press **SELECT** key to return to **ABOUT**.
4. Press the **UNITS** key...  
**DISP** is displayed. This is the display test item.
5. Press the **PRINT** key to perform a dynamic test of the display.
6. Press **ESC** key to stop the dynamic test.
7. Press the **UNITS** key...  
**BUTTON** is displayed. This is the button test item.

8. Press the **PRINT** key to perform a button test. Each key you press will be reflected on the display by a number to confirm the button is functioning correctly. See Table 1. The **ESC** key is excluded from this test. It is used to stop the testing and return to the menu item.

**Table 1**  
Key / Number Equivalents

Tare = 1	4 = 12
Select = 2	5 = 13
Zero = 3	6 = 14
Print = 4	1 = 17
Units = 5	2 = 18
F1 = 6	3 = 19
Power = 7	0 = 23
7 = 8	. = 24
8 = 9	C/CE = 20
9 = 10	Mode = 15

9. Press **ESC** key to stop the button test.  
**BUTTON** is displayed.
10. Press the **UNITS** key...  
**SERIAL** is displayed. This is the serial test item. To test the serial port, jumper the TX and RX lines. Continue to step 11.
11. Press the **PRINT** key to access the serial test.  
The display will show **FAIL** unless the TX and RX lines are jumpered or there is a problem with the serial port. **PASS** is displayed if the serial port is working properly.
12. Press **SELECT** key to exit the serial test.  
**SERIAL** is displayed.
13. Press the **SELECT** key...  
**TEST** is displayed.
14. Press the **UNITS** key...  
**AUDIT** is displayed.
15. Press the **PRINT** key...  
**CFG** is displayed. This stands for the configuration audit counter.
16. Press the **PRINT** key to see the number of times the configuration has been altered on this indicator.
17. Press the **SELECT** key...  
**CFG** is displayed.
18. Press the **UNITS** key...  
**CAL** is displayed. This stands for the calibration audit counter.
- Audit counters cannot be reset.*

19. Press the **PRINT** key. . .

The number of times the indicator has been calibrated is displayed.

20. Press the **ESC** key twice. . .

The display returns to normal operation mode.

This completes the User menu.







# Avery Weigh-Tronix

## Avery Weigh-Tronix USA

1000 Armstrong Dr.  
Fairmont, MN 56031 USA  
Telephone: 507-238-4461  
Facsimile: 507-238-4195  
e-mail: [industrial@weigh-tronix.com](mailto:industrial@weigh-tronix.com)  
[www.wtxweb.com](http://www.wtxweb.com)

## Avery Weigh-Tronix UK

Foundry Lane  
Smethwick, West Midlands  
England B66 2LP  
Tel: +44 870 90 34343  
Fax: +44 121 224 8183  
Email: [info@awtxglobal.com](mailto:info@awtxglobal.com)  
Web site: [www.awayweigh-tronix.com](http://www.awayweigh-tronix.com)

## Avery Weigh-Tronix Canada, ULC

217 Brunswick Boulevard  
Pointe Claire, QC H9R 4R7 Canada  
Telephone: 514-695-0380  
Toll free: 800-561-9461  
Facsimile: 514-695-6820  
[www.weigh-tronix.ca](http://www.weigh-tronix.ca)

Weigh Bar® is a registered trademark of Avery Weigh-Tronix and may be registered in certain jurisdictions.

All brands and product names used within this document are trademarks or registered trademarks of their respective holders.