PROGRAMMING FOR S2000-30KG-CA

1.   Make sure scale is **OFF**. Remove the platter and find the *CALIBRATION PORT* located on the front left side of the top cover.

2.   The *CALIBRATION PORT* is covered by two brass *SEALING BOLTS* and a silver plate. Remove the two *SEALING BOLTS* and the silver plate. You will see a red *MICRO SWITCH.*

3.   Slide the *MICRO SWITCH* to the right. Put the platter back on the scale.

4.   Turn scale **ON** and the *WEIGHT* display should flash   "CAL" three times and then go blank.

5.   Press the 4 key.

6.   Press the following keys: 8 key, the 7 key, and the C key.

7.   Press the following keys: 3 key, the 9 key, and the C key.

8.   Press the following keys: 2 key, the 0 key, and the C key.

9.   Press the following keys: 9 key, the 2 key, and the C key.

10.   Press the following keys: 0 key, the 7 key, and the   C key.

11.   Press the following keys: 0 key, the M3 key, and the   C key.

12.   Press the following keys: 0 key, the 8 key, and the   C key

13.   Once the scale displays go blank, press the 0 key. The scale will display Err 2

14.   Turn scale **OFF**, remove the platter, slide the *MICRO SWITCH* to the left, replace *SEALING BOLT* and silver plate, and replace the platter. You are done.