



# ELECTRICAL PPE REQUIREMENTS

**To:** Kevin Coombs, Jim Couch, Stewart Brown, Rob Bubnick, Steve Fortney, Mark Fracchia  
Jack Nagy, Shawn Munroe, Jeff Gaudette, Doug Beattie, Les Frehlich, Brent Cherkas, Brian Gotts, Sheldon Bolstad, All Potash Expansion EPCM Project Managers

**From:** Clark D. Bailey

**Date:** Dec 17, 2010

**Re:** **Clothing Requirements for Electrical Service Providers**

**CC:** Larry Simmons, Neil Wight, Cliff Rybchinski, Mike Hogan, Garth Moore

In the PotashCorp Workplace Electrical Guidance Document one of the sections dealt with service providers, and specifically with electrical service providers:

## ***Section 13***

### ***13.3 Personnel Protective Equipment***

*Electrical service providers are required to have their own PPE to protect from shock and arc flash hazards.*

*Electrical service providers must submit their PPE for inspection by PotashCorp upon request.*

***Note:*** *When requested, records of PPE life, inspections, and testing must be submitted. Records provided by contractors must be kept while the contractor is on site.*

Qualified Electrical employees of PotashCorp are currently required to wear a minimum level of PPE (8 cal/cm<sup>2</sup>) regardless of the work being performed. This allows our electrical workers to safely perform various non-energized/non-electrical and energized/electrical tasks throughout their shift. **In keeping with PotashCorp's high standard of safety, all electrical service providers are required to wear a minimum level of PPE (8 cal/cm<sup>2</sup>) while on site, regardless of the task being performed.**