# Intermec

SR60 Holster Instructions

Use the SR60 holster to conveniently attach the scanner to your belt, a forklift, or a post. The anti-skid material on the back of the holster helps keep it positioned correctly when you attach it to a forklift or a post.

The holster kit contains these parts:

- Holster accessory
- Two black zip ties
- This instruction sheet

To attach holster to your belt

1 Unsnap the flap on the back of the holster.

2 Place the holster over your belt and snap the flap back together. You can position the holster on either your right or left side.

**3** Insert the SR60 into the holster.

SR60 Holster: This illustration shows the SR60 inserted into the holster attached to a belt.

To mount the holster on a forklift or post

1 Unsnap the flap on the back of the holster.

2 Insert the two zip ties into the straps located on the back of the holster and snap the flap back into place.

3 Position the holster on a forklift or post and secure it with the two zip ties.

Anti-skid material

4 Insert the SR60 into the holster.

SR60 Holster Instructions

P/N 943-061-001 Rev A