Technical Bulletin

Please Distribute to all Sales and Service Personnel

Mettler-Toledo, Inc.
Scales & Systems

Number: R-7-99
Date: 6-8-99
Model: Intelli-Net
Subject: SmartTouch® Masters and Cutting Tests

When performing a cutting test on the 8305, 8360, or 8361 controller that is connected to a SmartTouch® Master Controller/Scale, each cutting test must have at least two PLUs. If the cutting test does not have at least two PLU records, then Intelli-Net will not collect the data from the master and Intelli-Net will display "file read" error.