Date: 15-JUL-04

The following describes the print server setup for the UADT/UATA/UATF models when the host PC is running the Windows XP operating system. It has been noted that when the print driver supplied with the Netgear FR114P is used with WinXP that the printing using the Netgear port is very slow. To increase the printing speed the following settings are recommended:

First create a new standard TCP/IP printer port and set as shown:

Other print settings are possible and may provide acceptable results.