

Issued August 2001
Replaces 9/99**MODEL 8000IS REPLACEMENT PARTS LIST**

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
SUB0138	<u>8000AIS Adapter Cable</u> Connects 8000AIS AC Power Supply to 8000MIS Indicator, two (2) foot length.	\$ 150.00
SUB0296	<u>8000AIS Interconnect Cable Plug</u> Male connector	\$ 50.00
SUB0297	<u>8000AIS Interconnect Cable Receptacle</u> Female connector	\$ 50.00
SUB0209	<u>Main PCB Assembly</u> For use on 8000MIS indicator, either the model 8000IS battery powered or model 8000ISAC line powered units. <i>There are no field serviceable components on this PCB - it must be replaced with a factory unit - no component level servicing is allowed.</i>	\$ 575.00
ENC0231	<u>“U” Bracket</u> Tilt stand bracket for use on 8000IS battery powered system indicator only. Use the standard “U” Bracket, P/N ENC0145-2 on the 8000ISAC line powered system indicator.	\$ 70.00
CNT0070	<u>Power Connector</u> Jack on 8000CIS, Male 3 Pin connector on the back of the indicator or battery charger. The connector on the end of the battery cable and the battery cable are to be factory serviced only.	\$ 30.00
SUB0301	<u>Touch Panel</u> Includes special lens assembly for use on 8000MIS indicator only. Applies to either Model 8000IS battery powered or 8000ISAC line powered unit. Refer to special installation instructions that come with this part to properly install it.	\$ 95.00
MAN0019	Dealer Manual	\$ 45.00

**Please Note: Factory level service is required for battery and cable
(See Service Page for Rates)**