## **Technical Bulletin**

Please Distribute to all Sales and Service Personnel

Mettler-Toledo, Inc. Scales & Systems

Page 1 of 1 Document: mtfw0400

Number: MTFW-04-00

Date: 03/31/00

**Model:** 645

**Subject:** CPU Boards

About 70 CPU boards P/N 14676700A were built missing the standoffs on the DB25 connector used to attach the Pocket and the labeler interface cable. If you received a machine or a service board with these standoffs missing order KOP 10856800A. This kit will supply you with the hardware required for one board.