

Technical Bulletin

Please Distribute to all Sales and Service Personnel

Mettler-Toledo, Inc.

Number: MTFW-09-00
Date: 04-12-00
Model: 645
Subject: Electronics Rack Fan Orientation

Beginning in late January the orientation of the cooling fan in the electronics rack assembly was changed. The fan is now reversed so it blows away from the boards. This was done to prevent dust accumulation on and around the components under the heat sink. If the accumulation of dust is conductive, it can cause the board to malfunction. This bulletin is just for informational purposes. No service is required on existing units.