

# Technical Bulletin

Please Distribute to all Sales and Service Personnel

**Mettler-Toledo, Inc.**  
**Scales & Systems**

**Number: MTFW-10-00**  
**Date: 04-20-00**  
**Model: 702**  
**Subject: Safe Handling Labels**

---

The roll size on the Safe Handling labels has been reduced from 5000 to 3500. This was done because there is not enough clearance around the take up spool for the liner from the 5000 label rolls. If your customer has 5000 label rolls in stock, have them remove the liner from the take up spool of the 702 each time they replace labels in the 317. The 317 labels have 2500 – 3500 per roll depending on label size. This will assure that the liner will not bind up the take up spool on the 702.