

Technical Bulletin

Please Distribute to all Sales and Service Personnel

Mettler-Toledo, Inc.
Scales & Systems

Number: MTFW-11-00
Date: 04-20-00
Model: 702
Subject: Package Discharge

There have been instances of labels getting lodged in the label chute on the 702 Bottom Label Applicator after the label guide upgrade. This condition is frequently caused by packages not properly discharging from the 702. It is very important that the rollers on the discharge conveyor and the accumulation table rotate freely and that these systems be set up with the proper pitch for efficient movement of the packages. If packages get hung up over the 702 label chute, labels will be forced back down the chute creating label feed problems.