




## WI-125/QTLTSC Troubleshooting Guide



**Figure 1**  
Box A  
Weight Sensor Simulator




**Figure 2**  
Box B




**Figure 3**  
Setup


# QTLTSC System Troubleshooting Sequence




# QTLTSC System Troubleshooting Sequence



# QTLTSC System Troubleshooting Sequence



# QTLTSC System Troubleshooting Sequence



**Weigh-Tronix**

1000 Armstrong Dr.

Fairmont, MN 56031 USA

Telephone: 507-238-4461

Facsimile: 507-238-4195

e-mail: [industrial@weigh-tronix.com](mailto:industrial@weigh-tronix.com)

[www.weigh-tronix.com](http://www.weigh-tronix.com)

**Weigh-Tronix Canada, ULC**

217 Brunswick Blvd.

Pointe Claire, QC H9R 4R7 Canada

Telephone: 514-695-0380

Facsimile: 514-695-6820

**WEIGH-TRONIX**

Weighing Products & Systems