


BÁSCULA PORTÁTIL DE MESA *HAWK* INSTRUCCIONES DE OPERACIÓN CONSIGNES D'UTILISATION DU TERMINAL *HAWK*



ENCENDIDO/APAGADO


ON/OFF



Pulse y mantenga por 3 segundos — Appuyez sur on/off et maintenez pendant trois secondes —


CERO

ZÉRO



NETO

NET




BRUTO

BRUT



PANTALLA ILUMINADA


AFFICHAGE RÉTROÉCLAIRÉ




Si usted tiene una pantalla iluminada — Si vous avez un affichage rétroéclairé —

IMPRIMIR

IMPRESSION




METTLER TOLEDO



A15731500A

HAWK[®] Scale OPERATING INSTRUCTIONS




ON/OFF


Press and hold for 3 seconds




ZERO



NET




GROSS




BACKLIT DISPLAY


If you have a backlit display —



PRINT



METTLER TOLEDO



A15731500A